RECEIVED

District I 1625 N. French Dr., Hobbs, NM 88240

FEB 06 2013 State of New Mexico Energy Minerals and Natural Resources

District II
811 S. First St., Artesia, NM 88210
NMOCD ARTESIA Conservation Division
District III
1000 Rio Brazos Road, Aztec, NM 87410

NMOCD ARTESIA Conservation Division
South St. Francis Dr.
Santa Fe, NM 87505

Submit one copy to appropriate District Office

Form C-129

Revised August 1, 2011

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

NFO Permit No. _ (For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

| | (See Rule 19 | .15.18.12 NMAC | and Rule 19.15.7 | .37 NMAC) | | | |
|--------------|--|--|------------------|-----------------|--------------------------------|---------------------------------------|--|
| | | | | | | | |
| A. | ApplicantCOG Operating | LLC | | | | · · · · · · · · · · · · · · · · · · · | |
| | whose address is _One Concho Center, 600 W. Illinois Ave., Midland, TX 79701, | | | | | | |
| | hereby requests an exception | to Rule 19.15.1 | 8.12 for | 216_ | 120 | days or until | |
| | August 6 | , Yr _2013_, for the following described tank battery (or LACT): | | | | | |
| | Name of LeaseWillow Yu | cca_ | Name of Pool | lFren; Glor | ieta-Yesc |) | |
| | Location of Battery: Unit Le | tter O | _Section16 | Township | 17S | Range31E | |
| | Number of wells producing in | nto battery31 | | | | , ,, , , | |
| В. | Based upon oil production of | 530 | | barrels per day | , the esti | mated * volume | |
| | of gas to be flared is1860_ | | MCF; Value | | | per day. | |
| C. | Name and location of nearest | gas gathering fa | acility: | | | | |
| | DCP | | | | | ···· | |
| D. | Distance | | | | | | |
| E. | This exception is requested for | or the following | reasons:Re | questing to ex | tend the t | ime for allowing to | |
| | flare At the Willow Yucca Ba | attery. DCP still | working to fix l | high line press | ure issue. | | |
| | | | | - | | | |
| | | allan er sesta anna anna anna anna anna anna anna a | | | | | |
| | | | | 5 | | | |
| OPERATOR | | | OIL CONSER | VATION DIV | ISION | • | |
| | that the rules and regulations of the O een complied with and that the inform | | | June | 20 - 1 | 20/3 | |
| | lete to the best of my knowledge and | | Approved Uin | " June of | $\mathcal{D} \cap \mathcal{O}$ | 2010 | |
| Signature | J- Li | | ву Л | []]\xo | le | | |
| Printed Name | | | (). | | 5 000 | | |
| & TitleBri | | : | Title // S | 1 | zzen | 1867 | |
| E-mail Addre | ess_bmaiorino@concho.com | | Date _ 2/0 | 0/13 | | | |
| Date 2/06/20 | 013 Telephone No. 43 | 32-221-0467 | | | | | |

Gas-Oil ratio test may be required to verify estimated gas volume.

Battery Name

| İ |
|---|
| İ |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |