RECEIVED

District I 1625 N. French Dr., Hobbs, NM 88240

FEB 06 2013 State of New Mexico Energy Minerals and Natural Resources

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

District II
811 S. First St., Artesia, NM 88210
NMOCD ARTESIA Conservation Division
District III
1000 Rio Brazos Road, Aztec, NM 87410

NMOCD ARTESIA Conservation Division
South St. Francis Dr.
Santa Fe, NM 87505 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

NFO Permit No. \_ (For Division Use Only)

## APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

	(See Rule 19.	.15.18.12 NMAC	and Rule 19.15.7	.37 NMAC)		
A.	ApplicantCOG Operating	rc			<u>.</u>	
	whose address is _One Concho Center, 600 W. Illinois Ave., Midland, TX 79701					
	hereby requests an exception	to Rule 19.15.1	8.12 for	210_	120	days or until
	August 6	Yr _2013	3_, for the follow	wing described	tank batter	y (or LACT):
	Name of LeaseWillow Yu	   cca	Name of Pool	Fren; Glori	eta-Yeso	•
	Location of Battery: Unit Let	tterO	_Section16	Township _	_17SR	Range31E
	Number of wells producing in	to battery31				
B.	Based upon oil production of	530		oarrels per day	, the estima	ted * volume
	of gas to be flared is1860_		MCF; Value			per day.
C.	Name and location of nearest	gas gathering fa	acility:			
	DCP					
D.	Distance	Estimated co	ost of connection	n		
E.	This exception is requested for	or the following	reasons:Rec	questing to exte	end the time	e for allowing to
	flare At the Willow Yucca Battery. DCP still working to fix high line pressure issue.					
				namental statement i i i i i i i i i i i i i i i i i i i		·
67ED + MAD						
OPERATOR	nat the rules and regulations of the Oi	l Conservation	OIL CONSERY			·
	en complied with and that the information		Approved Uni	Lung	30 - X	1/3
is true and compl	cte to the best of my knowledge and l	belief.	ripproved Chir		, ,	
Signature	Si hi		Ву	11 Sol	l	
Printed Name			Title Dist R Seperison			
& Title Brian Maiorino			Date 2/4	1/13	<i>y</i>	
	ss_bmaiorino@concho.com_	2 221 0467		<i></i>		
Date 2/06/20	Telephone No. 43	2-221-046/				

Gas-Oil ratio test may be required to verify estimated gas volume.

## **Battery Name**

Ductury rearrie						
Well#	API Number					
Willow St. 1	30-015-28880					
2	30-015-32664					
3	30-015-29606-/					
4	30-015-32844					
5	30-015-29495					
6	30-015-29609					
7	30-015-34143					
<b>8</b> .	30-015-34559 <sup>V</sup>					
9	30-015-36351					
10	30-015-37622√,					
11	30-015-37623 /					
12	30-015-37624					
13	30-015-37178 <sup>N</sup>					
14	30-0 <b>15-</b> 37176 √					
15	30-015-37050					
16	30-015-37638					
Yucca St. 1	30-015-29265					
2	30-015-29391					
3	30-015-29607					
5	30-015-37619					
6 .	30-015-37401					
7	30-015-37620					
8	30-015-37402					
9	30-015-37043					
10	30-015-37042					
11	30-015-37102					
12	30-015-37103					
13	30-015-37630					
14	30-015-37725					
15	30-015-37726					
16	30-015-37631					
	Ì					