Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECE&&E.

FEB 2 0 2013

FORM APPROVED OMB NO. 1004-0135

	Expires:	July	31,	2
Lease Seri	al No.			
	0 C C O T A			

Explies. July 31, 2010	
5. Lease Serial No. NMNM025527A	,

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter ARTESIA abandoned well. Use form 3160-3 (APD) for such-proposals.				NMNM025527A 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other ☐ Other					8. Well Name and No. BERRY A 29		
Name of Operator ALAMO PERMIAN RESOURCES LLCE-Mail: cstoker@helmsoil.com			ER		9. API Well No. 30-015-00472-0)-S1	. •
3a. Address 415 WEST WALL STREET SUITE 500 Ph: 43 MIDLAND, TX 79701			include area code) -7659 10. Field and Pool, or Explorate RED LAKE			Exploratory	
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description,				11. County or Parish, a	nd State	
Sec 23 T17S R27E SENW 19	80FNL 1980FWL			-	EDDY COUNTY	, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF 1	NOTICE, RI	EPORT, OR OTHER	R DATA	
TYPE OF SUBMISSION	·		TYPE O	ACTION			
□ Notice of Intent☑ Subsequent Report□ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans	□ New	ture Treat Construction and Abandon	☐ Reclam		☐ Water Shu ☐ Well Integ	
,	Convert to Injection	Plug		☐ Water I	***		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for 1/25/2013 Laid down polish rod, POOH NU BOP. RIH picking up 5 joi w/ (1) 4 ft 2 3/8 sub, then POG @1492'. 1/29/2013 Open BOP, well had 0 psi. RI to cement. Pumped 11 1/2 bb stands. Reversed out with fre wireline. RIH. Tagged cemen joints of tubing and packer, tri	ally or recomplete horizontally, rk will be performed or provide to operations. If the operation rebandonment Notices shall be file final inspection.) w/ 4' 8' 2' sub(5/8), (50) 5/ nts of 2 3/8 tbg and tagge DH into derrick w/ 41 joints H w/ 44 joints @1461'. Pusil=48 sx w/ 2% calcium. Shall shall be structured to set packer but could structure and correct.	give subsurface the Bond No. or sults in a multiple donly after all substances of the bond	locations and measu- file with BLM/BIA e completion or reco- equirements, included X 1.5 pump. NI H laying down 5 Closed BOP. S FW and broke of V water, pumper into derrick. Rig POOH with wirely stand trying to	red and true ve. Required sul Depth of the second of the s	pertical depths of all pertin bequent reports shall be new interval, a Form 316 n, have been completed, a pool of the pertinguish witched ill with 3 witched as to pluggin polity under bond is face restoration is c	ant markers and iffiled within 30 d. 0-4 shall be filed ind the operator land land land land land land land land	zones. ays once nas
	# Electronic Submission For ALAMO PERM mmitted to AFMSS for proc	MAN RESOUR	CES LLC, sent to	the Carlsba	ad		
Name (Printed/Typed) CARIE STOKER		Title REGUL	ATORY AF	FAIRS COORDINAT	OR		
Signature (Electronic	Submission)		Date '02/07/2	013	·		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By ACCEPT	ED		JAMES A TitleSUPERVI	AMOS SOR EPS		Date 02	2/17/2013
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the		Office Carlsba	d		•	

Additional data for EC transaction #197402 that would not fit on the form

32. Additional remarks, continued

but couldn't. Finaly set packer @ 8' below ground level. POOH with tubing into derrick and laid down packer. Closed BOP. Pumped FW trying to get a rate. Pumped 4 bbl and well pressured up to 200. Bled well down through bleed off lines. Pumped 1/2 bbl, psi went to 400. Bled well down. RIH w/ 15 joints below perfs and pump 5 bbl FW, got circulation. Switched to cement. Pumped 66 bbls = 278sx. Got cement back to surface. Shut pump down. ND BOP. Topped cement to surface with hose.

1/30/2013

Met w Joe from BLM. The welder cut off the 9 5/8 casing even with the surface casing. Cement was visable inside the 9 5/8 casing and between surface casing. Welder welded the well marker on.

2/05/2013

Backhoe pulled out all cellar boards and back filled cellar.