District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised March 17, 1999

30-015-00912

Release Notification and Corrective Action

			OPERAT	OR	[☐ Initial Report X☐ Final Report							
Name of Co			Contact Kent Whitmire										
Address P.			Telephone No. 505.677.3642										
Facility Na	ne Empir	Facility Typ	e Well	_									
Surface Ow	ner State	State Lease No.											
LOCATION OF RELEASE													
Unit Letter	er Section Township Range Feet from the North				North	h/South Line Feet from the Eas			/West Line County				
A	16	18	27E	330	N		969.5	w		Eddy			
NATURE OF RELEASE													
Type of Rele	ase Oil & V	Volume of Release 6.7 bbls Volume Recovered 4.0 bbls											
Source of Re	lease Stuffi	Date and Hour of Occurrence Date and 99.10.05 early morning 8:00 AM				Hour of Discovery 09.10.05							
Was Immedia Unknow		If YES, To Whom? Unknown											
By Whom?		Date and Hour Unknown											
Was a Water		If YES, Volume Impacting the Watercourse.											
		RECEIVED											
If a Watercou	irse was Imp						SEP 2 (0 2005					
	QCU-Antibox												
Describe Cause of Problem and Remedial Action Taken.*													
Pools assessment with a broad off and are assessed the staff a beautiful at the staff at the sta													
Back pressure valve plugged off and over pressured the stuffing box. Used a vacuum truck to pick up the free fluid.													
Describe Area Affronted and Cleanus Assiss Toler &													
Describe Area Affected and Cleanup Action Taken.*													
2' wide X 75'length X 1" deep (25% oil)													
7' wide X 15' length X 1" deep (25% oil) 10' wide X 55' length X 1" deep (25% oil)													
10' wide X 55' length X 1' deep (25% oil) 10' wide X 50' length X 1" deep (25% oil) Dusted spill area with caliche Review stuffing box leak detectors for pumping unit stuffing boxes.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
reucial, state,	federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION												
(0:	K	TIM GUM											
Signature:	am	\dashv	Approved by District Supervisor: by M2										
Printed Name	: Kellie D.		Approved by	District Supervis	or:Uy	IVAL 7	lik Ar	minoc					
Title: Scheduler						Approval Date: 10/2/05 Expiration Date: N				Date: NA			
Date: 09.19.	.05		Phone: 5	05.394.1600		Conditions of	Approval: NA			Attached			
Attach Addit		ts If Necessa										<u> </u>	