District I
1625 N. French Dr., Hobbs, NM 88240

District II
1301 W. Grand Avenue, Artesia NS 8826 2013

District III

内でU ARTESIA

Phone: 575-628-4121

Date: 2/21/2013

AKA = Called inay

\* Attach Additional Sheets If Necessary

eacherson (a)

1000 Rio Brazos Road

District IV

State of New Mexico

Inergy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Francis D Santa Fe, NM 87505 Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Name of Company: Oxy Permian LTD (192463) 192463 Contact: Chris Jones Address: 1502 W. Commerce, Carlsbad, NM 88220 Telephone No.: 575-628-4121 Facility Name: McKittrick 11-5 SWD Facility Facility Type: SWD Facility Surface Owner: Mineral Owner Lease No.: NM 53219 API#: 30-015-33611 LOCATION OF RELEASE County LEA Unit Letter Section Township Feet from the North/South Uine Feet from the East/West Line Range 11 **22S** 24E L Latitude 32.40989 Longitude 104.47355 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 3500 bbls Volume Recovered: 250 Source of Release: 8" Poly line split Date and Hour of Occurrence: Date and Hour of Discovery: 2/20/2013 2/20/2013 Was Immediate Notice Given? If YES, To Whom? Voicemail: OCD & BLM: Jim Amos Date and Hour: 2/20/2013 By Whom? CJ Summers (Oxy) Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☑ Yes ☐ No If a Watercourse was Impacted, Describe Fully.\* Produced fluids exited location and flowed into Little Water Draw, an ephemeral water course that runs only during precipitous events. Describe Cause of Problem and Remedial Action Taken.\* An 8" pipeline spilt at the 45 degree joint causing a release of approximately 3500 bbls of produced fluids. Emergency response included immediate shutin of the pipeline to stop leak and vac trucks on site to pick up all standing fluids. The pipeline will be repaired at a later date. Talon/LPE was contacted to complete the site assessment. Soil and water samples from the impacted area were collected to determine appropriate clean up actions. Describe Area Affected and Cleanup Action Taken.\* The area impacted was 3,676-feet down the draw and varied from 18" in some areas to 4-8 feet wide in others. Once laboratory results are available Talon will submit a detailed work plan. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file Certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition AMER acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or fegulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Signed By Printed Name: Chris Jone FEB 27 2013 Title: HES Specialist Approval Date: **Expiration Date:** E-mail Address: Christopher Jones@oxy.com Conditions of Approval: Attached [ Remediation per OCD Rule &

**Guidelines. SUBMIT REMEDIATION** 

PROPOSAL NO LATER THAN: