Submit I Copy To Appropriate District Office		State of New Mexico		Form C-103			
District I - (575) 393-6161	Energy, Minerals and Natural Resources		ral Resources	Revised August 1, 2011 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CON	EEDMATION	DIMICION	30-015-21			
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION			5. Indicate	e Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505				ATE FEE		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, NWI 87303			6. State Oil & Gas Lease No. K-1020			
87505 SUNDRY NOT	CICES AND REPOR	RTS ON WELLS		7 Lease 1	Name or Unit Agreement Na	ame	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				ARTESIA	STATE UNIT		
1. Type of Well: Oil Well 🔯 Gas Well 🔲 Other				8. Well N	8. Well Number 901		
2. Name of Operator				1	9. OGRID Number		
Alamo Permian Resources. LLC 3. Address of Operator					274841 10. Pool name or Wildcat		
415 W. Wall Street, Suite 500, Midland, TX 79701				Artesia; Queen-Grayburg-San Andres			
4. Well Location	,						
Unit Letter A: 10	feet from the N	line and 1310	feet from the	E line			
Section 23	Township 18	8S Range	27E	NMPM	County EDDY		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)							
The state of the s	Tide Sand		·				
12. Check	Appropriate Box	x to Indicate N	ature of Notice	, Report or	Other Data		
NOTICE OF I	NTENTION TO	· •	SUE	BSEQUEN	IT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				RK	☐ ALTERING CASING	G 🗌	
_	<u> </u>						
PULL OR ALTER CASING D. MULTIPLE COMPL CASING/CEMENT JOB COMMINGLE DOWNHOLE COMMINGLE							
DOWN IOLE COMMINGLE		;			•		
OTHER:					PRODUCTION		
13. Describe proposed or com					ient dates, including estimat Attach wellbore diagram of		
proposed completion or re		19.13.7.14 NIVIAC	. For Multiple Co	ompletions: 7	Attach welloore diagram of		
•				•			
03/15/13	ELL DOOLLAUTH	DUMP AND DO		CT A NIDINIO	WALVE AND TOLED TO		
MIRU AZTEC 523. UNHANG WELL. POOH WITH PUMP AND RODS. DROPPED STANDING VALVE AND TRIED TO PRESSURE TUBING. NO SUCCESS. ND WELLHEAD. NU BOP. TAGGED FILL AND TALLIED OUT OF THE HOLE.							
TAGGED FILL @ 2010'. SWISDOWE.							
02/10/12	, ,		•	•			
03/18/13 PU MULESHOE MUD ANCHOR	PERF SUR SEAT	TING NIPPLE !	ENDURANCE JO	NINT 8 ITS	TURING TAC AND 52 I	TS	
TESTING TO 5000 PSI. TOTAL							
BOP. NU WELLHEAD. SET TA	C WITH 6,000 LB	S TENSION. PI	REP TO RUN RO	DDS. SWISE	OON.		
<u>3/19/13</u>		i I		•			
RIH WITH RODS AND PUMP. (CHANGED OUT 2	; 20 ROD COUPL	INGS, HWO, CL	EANED LO	CATION. RDMO		
					DECENTED	7	
<u> </u>		r Barata Menderakan		<u> </u>	RECEIVED	4 37 1	
Spud Date:	<u></u>	Rig Release Da	ate:	reites e rese	MAR 2 5 2013		
SHEEK L			104 TK 1	KILOHYII J	23001.mm/02	ŀ	
- NO CALLERY TO SERVICE FOR	•				NMOCD ARTESIA	4	
I hereby-certify that the information	n above is true and o	complete to the b	est of my knowled	ge and belief	, (
1 600 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				: : :			
SIGNATURE COMO	Italian	TITLE Regi	ulatory Affairs Co	ordinator	DATE_03/20/2013		
Type or print name CARIE ST	OKER E-mail	A	KER@HELMSO		PHONE: <u>432.664.7659</u>		
APPROVED BY:							
Conditions of Approval (if any):	<u> </u>	TITLE AU	- I Sepenis	~	DATE 3/27/19		