Submit 3 Copies To Appropriate District	State of N	ew Mexico		Form C-103 October 25, 2005
District-f	State of New Mexico Energy, Minerals and Natural Resources		WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240			30-015-22913	
District II 1301 W. Grand Aver Stesser Find 88210	OIL CONSERV/	ATION DIVISION	5. Indicate Type of Lease	
			STATE 🗹 FEE 🔤	
District III 1000 Rio Brazos Rd. Azted RM 87410 District IV		St. Francis Dr. NM 87505	6. State Oil & Gas L	ease No.
1220 S. St. Francis DANA BEARTESIA	Ganta i C,	1111 07 000		647-363 647-368
87505 SUNDRY NOTICES A				Jnit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAI				
A DIFFERENT RESERVIOR. USE "APPLIC/			-	e Abo Unit 309/64
PROPOSALS.)	<b>-</b> ]		8. Well Number	005
1. Type of Well: Oil Well  Gas Well C. Name of Operator	Other	· · · · · · · · · · · · · · · · · · ·	9. OGRID Number	235
•	Corporation		9. OGRID Nulliber	00873
3. Address of Operator			10. Pool Name	
303 Veterans Airpark Lane	, Ste. 3000, Midland,	TX, 79705	En	npire Abo
4. Well Location Unit Letter <b>G</b> :	1750 feet from the	N line and	1600 feet from	n the <b>E</b> line
	Township 18S	Range <b>28E</b>	NMPM	County Eddy
алан ал ан ал ан ал ан	levation (Show whether			
	36	672.9' GR	deren and the second	
12. Check Appropriate Box To Indicate N	lature of Notice, Report	rt, or Other Data		
TEMPORARILY ABANDON	AND ABANDON	REMEDIAL WORK COMMENCE DRILLING C CASING/CEMENT JOB		NG CASING
OTHER:		✓ Location is	ready for OCD inspect	ion after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
<ul> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> <li>A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the</li> </ul>				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from the lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)          Image: All other environmental concrens have been addressed as per OCD rules.         Image: Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from				
non-retrieved flow lines and pipelines.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.				
SIGNATURE Len Lelle	TITLE	P&A Technie	cian DATE	3/7/13
TYPE OR PRINT NAME Leon Sel	lers E-MAIL	leon.sellers@apach	ecorp.com PHONE	E: 432-208-0349
For State Use Only				
APPROVED BY: June U. June TITLE C. O. DATE <u>3/29/13</u> Conditions of Approval (if any):				