

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

WELL API NO.	30-015-04098
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	NM-7752
7. Lease Name or Unit Agreement Name	DREWERY FEDERAL
8. Well Number	001
9. OGRID Number	236183
10. Pool name or Wildcat	Square Lake Grayburg San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	3692' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator	TANDEM ENERGY CORPORATION
3. Address of Operator	2700 Post Oak Blvd. Ste 1000 Houston, Texas 77056
4. Well Location Unit Letter C : 330 feet from the N line and 1980 feet from the W line Section 6 Township 17S Range 30E NMPM County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3692' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Repaired electrical control panel for the pumping unit's motor. Restored the well to production, November, 2011.

Note: Since a notice of intent was not filed before the work was done, Daniel Sanchez with Enforcement in Santa Fe said to file a subsequent report.



Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Arnold TITLE Production Engineer DATE 4/5/2013

Type or print name Rusty Arnold E-mail address: rarnold@platenergy.com PHONE: 713-364-7822

For State Use Only

APPROVED BY: R Wade TITLE Dist # Supervisor DATE 4/11/13

Conditions of Approval (if any):