

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-10379
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator TANDEM ENERGY CORPORATION		6. State Oil & Gas Lease No. NM-27279
3. Address of Operator 2700 Post Oak Blvd. Ste 1000 Houston, Texas 77056		7. Lease Name or Unit Agreement Name ELLIOTT
4. Well Location Unit Letter G : 1980 feet from the N line and 1980 feet from the E line Section 29 Township 18S Range 30E NMPM County EDDY		8. Well Number 003
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3448' GR		9. OGRID Number 236183
		10. Pool name or Wildcat North Benson Queen Grayburg

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Rigged up pulling unit on the well to repair tubing leak. Pulled out of the hole with rods, pump and tubing. Pressure tested the tubing going in the hole. Replaced the joints of tubing that did not hold pressure. Ran in hole with pump and rods. Spaced out the pump and hung the well on. Restored to production, February, 2011.

NOTE: Since a notice of intent was not filed before the work was done, Daniel Sanchez with Enforcement in Santa Fe said to file a subsequent report.



Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Arnold TITLE Production Engineer DATE 4/5/2013

Type or print name Rusty Arnold E-mail address: rarnold@platenergy.com PHONE: 713-364-7822

For State Use Only

APPROVED BY: AR Wade TITLE Asst. Supervisor DATE 4/11/13

Conditions of Approval (if any):