


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW 1310139275 OPERATOR ☒ Initial Report ☒ Final Report


Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	DODD FEDERAL UNIT #10 B (580)	Facility Type	TANK BATTERY
Surface Owner	FEDERAL	Mineral Owner	Lease No. (API#) 30-015-39278

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	10	17S	29E					EDDY

Latitude 32.84282 Longitude 104.05513

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	14bbls
Source of Release	1/4" valve at circulating pump		Date and Hour of Occurrence	03-19-2013	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		Date and Hour of Discovery	03-19-2013 3:00pm	
By Whom?			If YES, To Whom?		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If YES, Volume Impacting the Watercourse.		
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Roustabout crew making repairs to circulating pump left open a 1/4" valve. Roustabout need to pay more attention and close valve to prevent further release.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 15bbls of oil were released from a 1/4" valve that was left open and we were able to recover 14bbls with a vacuum truck. All free fluid has been recovered. The spill was contained within the lined facility. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor:			
Title: Senior Environmental Coordinator		Approval Date:		Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 03-25-2013		Phone: 432-212-2399			

* Attach Additional Sheets If Necessary

2RP-1613

Accepted for record
NMOCD