

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 26 2013

Form-C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 1309836443

Name of Company: Apache Corporation	873	OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: PO Box 1849 Eunice NM 88231		Contact: Natalie Gladden	
Facility Name: Empire Abo Unit G312 (near Washington 33-#53)		Telephone No.: 575-390-4186	
		Facility Type: Production	

Surface Owner State	Mineral Owner State	Lease No. 30-015-40077
---------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	33	17S	28E	2290	FSL	2175	FEL	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: Oil/Water	Volume of Release: 300	Volume Recovered: 225
Source of Release: Emulsion Line	Date and Hour of Occurrence: 6/10/12	Date and Hour of Discovery: 06/10/12
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Natalie Gladden	Date and Hour: 06/14/12	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*




Describe Cause of Problem and Remedial Action Taken.\*

Fiberglass line leak. A local contractor found the leak at 10:40pm. Fiberglass line was repaired, Standing fluid was recovered and one-call was made.

Describe Area Affected and Cleanup Action Taken.\*

NMOCD Rules and Regulation will be followed to closure of the release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District Supervisor: 	Signed By: 
Title: EHS Environmental Tech	APR 08 2013	Approval Date: _____ Expiration Date: _____
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 06/25/12 Phone: 575-390-4186	May 8, 2013	2RP-1601

\* Attach Additional Sheets If Necessary