

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 20 2013

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1309548780 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	OWL 20504 JV-P WELL #005	Facility Type	SWD
Surface Owner	FEDERAL	Mineral Owner	
		Lease No. (API#)	30-015-35135

LOCATION OF RELEASE

35435

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	26S	27E					EDDY

Latitude 32.04148

Longitude 104.22825

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	0bbls
Source of Release	Fiberglass line	Date and Hour of Occurrence	03-10-2013	Date and Hour of Discovery	03-10-2013 4:45pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



The buried fiberglass line fractured due to traffic. The line has been replaced and added more surface material for additional padding and protection.

Describe Area Affected and Cleanup Action Taken.\*

Initially an estimated 10bbls were released due to a fracture in a buried fiberglass line on location. We were unable to recover any fluids. The entire spill was contained on the location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD/BLM acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	
Printed Name:	Josh Russo	Signed By 	
Title:	Senior Environmental Coordinator	Approval Date:	APR 05 2013
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	03-20-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-212-2399		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:

May 5, 2013

2RP-1599