

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 19 2013

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA  
Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO STATE UNIT #18H	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	
		Lease No. (API#)	30-015-39999

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	28E					EDDY


Latitude 32.04888

Longitude 104.10211

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	18bbls
Source of Release	Fire tube	Date and Hour of Occurrence	03-06-2013	Date and Hour of Discovery	03-06-2013 10:30am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The fire tube on the heater treater developed a hole due to corrosion. Fire tube has been replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of produced water were released from a hole in the fire tube on the heater treater inside the facility. We were able to recover 18bbls with a vacuum truck. The release was completely contained inside the lined facility walls of the tank battery. All free fluid has been recovered. Any contaminated gravel has been removed and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:		Accepted for record NMOCD
Printed Name:	Josh Russo	APR 05 2013		
Title:	Senior Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address:	jrusso@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	03-19-2013	Phone:	432-212-2399	

\* Attach Additional Sheets If Necessary

2RP-1598

Accepted for record  
NMOCD