

30-015-40998

RECEIVED
APR 0 2013
CD AC

WELL NAME AND NUMBER Lea C Federal 19
LOCATION Section 11, T17S, R31E, NMPM, 1210 FNL, 1310 FWL, Eddy County
OPERATOR Capstone Resources, LLC
DRILLING CONTRACTOR United Drilling, Inc.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and had conducted deviation test and obtained the following results:


Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
.8° @ 397'		
.7° @ 671'		
.5° @ 1062'		
2.0° @ 1538'		
1.9° @ 2008'		
.5° @ 2488'		
.2° @ 2961'		
.7° @ 3436'		
1.4° @ 3909'		
1.0° @ 4416'		

Drilling Contractor- UNITED DRILLING, INC.

By: 
(Luisa Noriega)

Title: Assistant Office Manager

Subscribed and sworn to before me this 5th day of February 2013.


Notary Public
Chaves New Mexico
County State

My Commission Expires: 10/8/14