District I.
1625 N. French Dr., Hobbs, NM 88240
District II.
1301 W. Grand Avenue, Antesia, NM 88210
District III.
1000 Rio Brazos Road, Azrec, NM 87410
District IV.
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

DIM!	W 1310	02531				on and Corrective Acti RATOR			Initia	l Report	Ø	Final Report
Name of Company OGRID Numb						Contact						
Yates Petroleum Corporation 25575						Robert Asher						
Address 105 S. 4 <sup>Th</sup> Street						Telephone No. 575-748-1471						
Facility Name API Number						Facility Type						
Cigarillo SWD #1 30-015-21643						SWD Battery						
Surface Ow				Mineral O	· · · ·	Lease No.						
State State								VO-7290				
				I.OCA'	TIO	NOFER	LEASE	·				
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
c	36	235	27Ē	1980		North	1980	Eas		Eddy		
erandestandes			5 <del>7,784, 554</del> 7	Latitude 32.2	6322	Longitud	e <u>104.14136</u>					
	·			NATI	JRE	OF REL	EASE					
Type of Release						Volume of Release			Volume Recovered			
Produced Water Source of Release						390 B/PW Date and Hour of Occurrence			390 B/PW Date and Hour of Discovery			
Transfer Pun	mp	:			3/18/2013; AM 3/18/2013; AM							
Was Immedia	ate Notice (		Var E	No ☐ Not Req	i	If YES, To Whom?  ed Mike Bratcher/NMOCD District II						
By Whom?		·	I NO LI NOLKA	(un ev	Date and Hour							
Robert Asher	/ Yates Peti	roleum Corpo		3/20/2013; AM								
Was a Water		hed?			If YES, Volume Impacting the Watercourse.							
If a Watercou	ree was Im		Yes 🗵			N/A						
N/A			<u>ک</u> د	<u>tan</u> akara wata .			Manager F. C. V 155 Company of the Company of th		-		<del></del>	
Describe Cau												
Describe Are				n truck called:					<del></del>	·		
An approxima	ate area of 3	30' X 100' (iv	side berm	ed and lined battery	/). Al	l released prod	luced water was re	ecov <del>ere</del> d. I	Depth to	Ground V	Vater:	50-99' (75',
ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on all produced water being recovered and battery is lined, Yates Petroleum Corporation requests closure.												
I hereby certif	fy that the i	nformation gi	ven above	is true and comple	te to 1	the best of my	knowledge and u	nderstand t	hat purs	uant to NM	OCD r	ules and
regulations all	l operators	are required to	report an	d/or file certain rele c of a C-141 report	ease i	otifications ar	nd perform correct	tive actions	for rele	eses which	may e	ndanger
should their o	perations hi	ave failed to a	dequately	investigate and ren	nedia	te contamination	on that pose a thre	at to groun	id water	. surface wa	ater, hu	man health
or the environ federal, state,	ment. In a	ddition, NMO	CD accep	tance of a C-141 re	port c	loes not relieve	e the operator of r	esponsibili	ty for co	mpliance v	with an	y other
teneral, state,	OT TOCAL 180	o and or regu	ignions.	· · ·	-1		OIL CONS	SERVAT	LION	DIVISIO	)N	
<b>5</b> 1 .		$\mathcal{I}$	OIL CONSERVATION DIVISION									
Signature:		E JAI	<u> </u>	-	Approved by District Supervisor:							
Printed Name	Robert As	her				Approved by	District Superviso	)T				
Title: NM En	vironmental	Regulatory S		Approval Date: NA								
E-mail Addres			.41, 4	The same of the same		Conditions of Approval: NA						
Date: Friday,			none: 575-	.748_4021		2RP- Attached  Attached						
Attach Addit				1707021		- LIVI -			<del></del>		<del></del>	100
			•							ZKt	1-/(	0'LU