

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

APR 16 2013

NMOCD ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737		Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: Big Eddy Unit 122		Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27454

#### LOCATION OF RELEASE

Unit Letter F	Section 4	Township 20S	Range 31E	Feet from the 1980	North/South Line North	Feet from the 1980	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.604160 Longitude W 103.876110

#### NATURE OF RELEASE

Type of Release: Produced water	Volume of Release 25 bbls	Volume Recovered: None
Source of Release	Date and Hour of Occurrence 4/12/13 Time unknown	Date and Hour of Discovery 4/12/13 1:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Emergency NMOCD number #104	
By Whom? Tony Savoie	Date and Hour 4/12/13 1:58 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A valve was found open on the produced water tank on the location, the well is not on production. The cause of the release is under investigation. The tank valve was shut.

Describe Area Affected and Cleanup Action Taken.\* Approximately 2700 sq. ft. of the caliche well pad was affected by the release. No remediation has taken place at this time. The spill will be cleaned up in accordance to the NMOCD and BLM guidelines on spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: By Mike Benavides	
Title: Waste Management and Remediation Specialist		Approval Date: APR 17 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 4/16/13	Phone: 432-556-8730		

\* Attach Additional Sheets If Necessary

May 17, 2013

2RP-1623