

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

APR 16 2013

NMOCD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1310754297

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: North Indian Flats 26 Federal #1	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-105-27556
------------------------	------------------------	----------------------

LOCATION OF RELEASE

015

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	26	21S	28E	2150	North	1980	East	Eddy

Latitude N 32.452530 Longitude W 104.054850

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 25 bbls	Volume Recovered: None
Source of Release 3" water dump line	Date and Hour of Occurrence 4/4/13 time unknown	Date and Hour of Discovery 4/4/13 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The 3" water dump line from the heater-treater to the water tank developed a leak due to internal corrosion. A repair clamp was placed on the affected area of the pipe.

Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 5800 sq. ft. of caliche well pad and tank battery pad. The saturated soil was scraped and stockpiled on site pending further remediation activities. The spill area will be remediated following the NMOCD and BLM guidelines for spills and releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: Signed By Mike Benavides	
Title: Waste Management and Remediation Specialist		Approval Date: APR 17 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: May 17, 2013	Attached <input type="checkbox"/>
Date: 4/16/13 Phone: 432-556-8730			

* Attach Additional Sheets If Necessary

2RP-1624