

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 29 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SHOWSTOPPER 7 FEDERAL COM #001H	Facility Type	WELL PAD

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-36659
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

*36559

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	07	25S	29E					EDDY

Latitude 32.15112 Longitude 104.01676

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	3bbls oil 15bbls produced water	Volume Recovered	2bbls oil 12bbls produced water
Source of Release	Well packing	Date and Hour of Occurrence	04-15-2013	Date and Hour of Discovery	04-15-2013 6:45am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Well packing failed due to high flowline pressure caused by a compressor shutting down. We have replaced the well packing.

Describe Area Affected and Cleanup Action Taken.*

Initially 3bbls of oil and 15bbls of produced water were released due to high pressure in flowline causing the packing to fail. We were able to recover 2bbls of oil and 12bbls produced water with a vacuum truck. The spill was completely contained on location. All free fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor:	
Title: Senior Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		Attached <input type="checkbox"/>
Date: 04-29-2013	Phone: 432-661-6601		

* Attach Additional Sheets If Necessary

June 3, 2013

2RP-1641