


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*nJMW1314040088*

**OPERATOR**  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	HAMBONE FEE COM #001H	Facility Type	TANK BATTERY

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-38980
---------------	---------	---------------	--	------------------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	05	26S	29E					EDDY

Latitude 32.06615 Longitude 104.01392

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	100bbbs	Volume Recovered	99bbbs
Source of Release	Bleeder valve on filter pot	Date and Hour of Occurrence	05-06-2013	Date and Hour of Discovery	05-06-2013 4:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	05-07-2013 4:45pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Bleeder valve was left open on filter pot after the water pump had been serviced. Shut the valve to prevent further release.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 100bbbs of produced water were released due to the filter pot valve being left after the water pump was serviced. We were able to recover 99bbbs of produced water with a vacuum truck. The spill was completely contained in a lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned, and we have replaced with fresh gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	Senior Environmental Coordinator	Approval Date:	MAY 20 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	05-14-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-661-6601		

\* Attach Additional Sheets If Necessary

*2RP-1653*