

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**Operator** ☒ Initial Report ☐ Final Report

**Name of Company** Oxy Permian **Contact** C.J. Summers  
**Address** 102 S. Main St. Carlsbad, NM 88220 **Telephone No.** 575-397-8216  
**Facility Name** SDS 11 Federal 1 SWD Battery **Facility Type** SWD

**Surface Owner** BLM **Mineral Owner** BLM **API No.** 30-015-27627


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	24S	31E	2090	North	1980	West	Eddy

**Latitude** 32.23339 **Longitude** -103.75070

NATURE OF RELEASE

<b>Type of Release</b> Produced Water	<b>Volume of Release</b> 20 bbls	<b>Volume Recovered</b> 0 bbls
<b>Source of Release</b> Transfer Pump	<b>Date and Hour of Occurrence</b> May 13, 2013 Time: Unknown	<b>Date and Hour of Discovery</b> May 13, 2013 Time: Unknown
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Jim Amos of the BLM and Mike Bratcher of NMOCD	
<b>By Whom?</b> C.J. Summers	<b>Date and Hour</b> 5/15/2013 @ 1:38 pm	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse.</b>	



**If a Watercourse was Impacted, Describe Fully.\***

**Describe Cause of Problem and Remedial Action Taken.\***

The release was due to a leak on the triplex transfer pump line. Initial remedial actions will be conducted by Oxy. Talon/LPE was contracted to perform an initial site assessment and soil sampling. Upon receipt of analytical results from the soil sampling activities a work plan will be drafted and remedial activities will begin upon its approval.

**Describe Area Affected and Cleanup Action Taken.\***

The fluid from this release flowed north and west across the location. The fluid ran off of the Northern side of the location and flowed into the pasture for approximately 280-feet. Talon/LPE collected soil samples on the location as well as in the flow path running in the pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

<b>Signature:</b>	<b>Approved by Environmental Specialist:</b>	
<b>Printed Name:</b> C.J. Summers	<b>Signed By</b>	<b>Approval Date:</b> JUL 03 2013
<b>Title:</b> HES Advisor	<b>Expiration Date:</b>	
<b>E-mail Address:</b> Chancey_Summers@oxy.com	<b>Conditions of Approval:</b> Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 6-20-13 <b>Phone:</b> 575-397-8216	<b>PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

August 3<sup>rd</sup>, 2013

2RP-1704