

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 28 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NTM *1318452944*

Name of Company		COG OPERATING LLC <i>229137</i>		Contact	Pat Ellis	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701		Telephone No.	432-230-0077		
Facility Name		GEHRIG FEDERAL COM #005H		Facility Type	TANK BATTERY		
Surface Owner		FEDERAL		Mineral Owner		Lease No. (API#) 30-015-37678	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	09	26S	29E					EDDY

Latitude 32.05086 Longitude 103.98149

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	3" line	Date and Hour of Occurrence	06-16-2013	Date and Hour of Discovery	06-16-2013 5:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A 3" line failed going from the heater treater to the produced water tank. The line has been replaced to prevent any reoccurrences.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of produced water were released due to a 3" line from the heater treater to the produced water tank. We were able to recover 19bbls of produced water with a vacuum truck. The spill was completely contained inside the lined facility walls. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned, and we have replaced with fresh gravel as necessary. This facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:	<i>Robert Grubbs Jr.</i>	Approved by District Supervisor:		Signed By <i>Mike Brannon</i>
Printed Name:	Robert Grubbs Jr.	Approval Date:		Expiration Date:
Title:	Senior Environmental Coordinator	JUL 03 2013		
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	06-28-2013	Phone:		432-661-6601

* Attach Additional Sheets If Necessary

Like approval by
BLM

2RP-1708