District I
1625 N. French Dr., Höbbs, NM 88240
District II
1301 W. Grand Avenué, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

JUL 09 2013

Form C-141 Revised October 10, 2003

NMOCD ARTES PAdpies to appropriate Definition of the Park Price in accordance with Rule 116 on back side of form

2RP-1721

Release Notification and Corrective Action													
						ATOR	, s <sup>-1</sup>						
Name of Company OGRID Numb					nber	Contact.							
Yates Petroleum Corporation 25575						Amber Cannon							
Address 104 S. 4 <sup>TH</sup> Street						Telephone No. 575-748-1471							
Facility Name API Number						Facility Type							
Wyatt BHT State #1 30-015-34553						Well							
Surface Owner Mineral Ow					Owner				Lease No.				
State				State					VO-6699				
LOCATION OF RELEASE													
Unit Letter   Section   Township   Rang		Range			th/South Line   Feet from the   E			Vest Line	County				
В	B 6 25S 30E		30E	330		North	2310'	I	East	Eddy			
Latitude_32.16557 Longitude_103.9192_													
NATURE OF RELEASE													
Type of Release						Volume of		Т	Volume Recovered				
Produced Water/Crude Oil/Gas						4 B/PW, 1 B/O, 5 MCF Gas			None				
Source of:Release						Date and Hour of Occurrence			Date and Hour of Discovery				
Poly Flow Line Was Immediate Notice Given?						6/27/2013; AM 6/27/2013; To Whom?				2013; PM			
Yes No Not Require													
By Whom?						Date and Hour							
N/A						N/A							
Was a Watercourse Reached?  ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse. N/A							
If a Watercou	ırse was İmp												
N/A Describe Cau	ise of Proble	m and Reme	Jial Action	n Taken.*									
High pressure	Describe Cause of Problem and Remedial Action Taken.*  High pressure and heat caused a poly flow line to rupture in a weak spot in the line, causing fluid to leak on to the lease road. The leak was isolated upon discovery and the poly line was fixed.												
Describe Are	a Affected a	ind Cleanup A											
				on the lease road.									
the mesquite bushes will be sprayed with 8% microblaze upon one-call clearance. Depth to Ground Water: >100' (approximately 250', Section 6, T25S-R30E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on release													
				unt released, Ya							0.00	· . · · · · · · · · · · · · · · · · · ·	
regulations al	ty that the ir	itormation gi ire required to	ven above renort an	is true and completed or file certain re	lete to ti elease n	he best of my	knowledge and u	nderstan tive activ	d that purs	uant to NM	OCD r	ules and	
public health	or the enviro	onment. The	acceptanc	c of a C-141 repo	rt by the	e NMOCD m	arked as "Final Re	eport" de	es not reli	eve the ope	rator of	fliability	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
OIL CONSERVATION DIVISION													
10: 10 ho. C. 22.52													
Signature: (UMDEL (annon													
Printed Name: Amber Cannon						Approved by District Supervisor: Signed By Mily Beautier							
Title: Environmental Regulatory Agent						.1111 1 5 2013				piration Date:			
E-mail Address: acannon@yatespetroleum.com									•				
3						Conditions of Approval:				Attached			
Date: Tuesday	/ July 09 20	013	Phone: 57	5.748.4111	1 '	ንጽቦ_							