

RECEIVED

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources 10 2013
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

WJM 1319733310 OPERATOR Initial Report Final Report

Name of Company Oxy Permian 16696	Contact Chris Jones
Address 102 S. Main St. Carlsbad, NM 88220	Telephone No. 575-628-4121
Facility Name Roo 22 State #1	Facility Type Oil Well
Surface Owner: State	Mineral Owner: State
API No. 30-015-39370	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	22	17S	28E	1289	South	693	West	Eddy

Latitude 32.8163103580893 Longitude -104.17004771578

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release 15	Volume Recovered 0
Source of Release Flow Line	Date and Hour of Occurrence July 2, 2013 12:00p	Date and Hour of Discovery July 2, 2013 12:00p
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher of NMOCD & Jim Amos of BLM	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A 4 inch poly flowline was damaged when CVE Electric Co. drilled to place a power pole and drilled through the line. The volume of the leak was 3 bbls of oil and 12 bbls of produced water. Talon/LPE was contracted to perform an initial site assessment and soil sampling. Upon receipt of analytical results from the soil sampling activities a work plan will be drafted and remedial activities will begin upon its approval.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 40' X 20'. This area includes impacts on the location and pasture land.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist:	Signed By: 
Title: HES Specialist	Approval Date: JUL 16 2013	Expiration Date:
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-10-13 Phone: 575-628-4121		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

August 16, 2013

2RP-1722