

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUL 29 2013

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

JMW 1321049818

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	192463	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM		Telephone No.	(575) 628-4121
Facility Name	Nagooltee Peak 5 Federal #2		Facility Type	

Surface Owner	BLM	Mineral Owner		API No.	30-015-28074
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	5	22S	24E	1562	North	1202	West	Eddy County, NM

Latitude N 32.42378° Longitude W 104.52532°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	60 bbls	Volume Recovered	0 bbls
Source of Release	Hole in steel flow line	Date and Hour of Occurrence	07/11/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Jean Marie Warren- OCD, James Amos- BLM		
By Whom?	Christopher Jones	Date and Hour	07/12/2013 @ 10:54 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A hole in a steel flow line caused 60 bbls of produced water to leak onto the ground. No fluids were recovered. The line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 200' x 60'. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Christopher Jones	Approved by District Supervisor	Signed By	<i>Mike Bratcher</i>
Title: HES Specialist	Approval Date: JUL 29 2013	Expiration Date:	
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 7-29-13 Phone: (575) 628-4121	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		

\* Attach Additional Sheets If Necessary

August 29, 2013

2RP-1767