				RECEIVED	
Submit One Copy To Appropriate District	State of New M	Mexico		JUL 26 ROFF C-103	
Office District I	Energy, Minerals and Natural Resources			Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL APL	NOVOCD ARTESIA	
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-21812 5. Indicate Type of Lease		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE X		
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name Jackson Estate BY	
1. Type of Well: Oil Well Gas Well X Other P&A			8. Well Number #7		
2. Name of Operator			9. OGRID	Number	
Yates Petroleum Corporation 3. Address of Operator			025575	10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210			Eagle Creek; San Andres		
4. Well Location			1	,	
	feet from the No	orth line and	1650fe	et from the <u>West</u> line	
Section 22 Township 17S Range 25E NMPM Eddy County					
	11. Elevation (Show whether L				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INT	ENTION TO:	SUB	SEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				☐ ALTERING CASING ☐	
				_	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB		
OTHER:		☐ Location is r	eady for OCD	inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.					
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the					
A sleet market at least 4 in diameter and at least 4 above ground level has been set in concrete. It shows the					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR					
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
The location has been leveled as a	nearly as possible to original gr	ound contour and has	been cleared of	of all junk, trash, flow lines and	
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with					
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed					
from lease and well location. All metal bolts and other materials	s have been removed. Portable	bases have been remo	oved. (Poured	onsite concrete bases do not have	
to be removed.)			,		
All other environmental concerns			A 11 Alicida lica	1	
Pipelines and flow lines have bee retrieved flow lines and pipelines.	n adandoned in accordance wit	II 19.13.33.10 NMAC	. All fluids na	ive been removed from non-	
If this is a one-well lease or last re	emaining well on lease: all elec	trical service poles ar	nd lines have b	een removed from lease and well	
location, except for utility's distribution	n infrastructure. Company	has been notif	ied to Re	move poles	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.					
SIGNATURE Tuy	CBTITLE	Environmental S	siendist	DATE 7/23//3	
TYPE OR PRINT NAME Amore For State Use Only	la Trujillo E-MAI	L: atrujilbeya	atespetrole	maPHONE:(575)748-1471	
	1- June TITI F	A s		DATE 8/12/12	
APPROVED BY: Conditions of Approval (if any):	1 TO RESTER	<u> </u>		DATE OFF	
OR	- 10 1-0 00 119	<u>_</u>			