Submit 3 Copies To Appropriate District Office	State of N	ew Mexico		Form C-103 October 25, 2005
District I	Energy, Minerals and	d Natural Resources	WELL API NO.	
1625 N. French Dr. Hobbs ANTER HOBBS OGTO CONCERNATION DIVISION			30-015-02607	
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease	
Disrtict III 1000 Rio Brazos Rd. Aztec, NM 87410 AUG 2 3 2013 1220 South St. Francis Dr.			STATE 🗹	FEE
District IV Santa Fe. NM 87505			6. State Oil & Gas Lease	No.
1220 S. St. Francis Dr. Santa Fe, NM				
87505 RECEIVED» SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO			Empire Abo Unit "I"	
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.) , 1. Type of Well: Oil Well 🗹 Gas Well 🗌 Other			8. Well Number 25	
2. Name of Operator			9. OGRID Number	
Apache Corporation			00873	
3. Address of Operator			10. Pool Name	
303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705 4. Well Location			Empire Abo	
Unit Letter D :	660 feet from the	N line and	660 feet from the	W line
Section 5	Township 18S	Range 28E	NMPM	County Eddy
11	. Elevation (Show whether I	DR, RKB,RT, GR, etc. ) 682' GR	A set of the set of th	
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data				
	_	1	SUBSEQUENT REP	P
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A SUBJECT OF ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
OTHER:		✓ Location is r	eady for OCD inspection of	tor P&A
OTHER:				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
<ul> <li>Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> <li>If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with</li> </ul>				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from the lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
All other environmental concrens have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
When all work has been completed, return inspection has to be made to a P&A locat				-
Inspection has to be made to a Par locat	on because it does not meet th	le chteria above, a penaity n	lay be assessed.	
SIGNATURE Zem Selles	TITLE	P&A Technici	an DATE .	8/21/13
TYPE OR PRINT NAMELeon S	ellers E-MAIL	leon.sellers@apache	corp.com PHONE:	432-208-0349
For State Use Only	· · · ·	<b>A</b> .		
APPROVED BY:	. Sim TITLE	C. C.	DATE	10/10/13
Conditions of Approval (if any):	J. Samuelle			,
OKJU RE	SUEAGE.			

•