

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 01 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJM 1327640141

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Stinking Draw #002	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-27976
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	36	20S	23E	660	South	1980	West	Eddy County, NM

Latitude N 32.51669° Longitude W 104.5581°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	1 bbls of oil and 15 bbls of water	Volume Recovered	0 bbls
Source of Release	1/2" Nipple broke off of the well head	Date and Hour of Occurrence	09/12/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD, James Amos and Jennifer VanCuren- BLM		
By Whom?	Christopher Jones	Date and Hour	09/13/2013 @ 3:42 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A half inch nipple broke off of the well head causing 1 bbls of oil and 15 bbls of produced water to leak on to the ground. No fluids were recovered and the nipple was replaced on the well head.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 100'. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Christopher Jones

Title: HES Specialist

E-mail Address: Christopher.Jones@oxy.com

Date: 9/30/13

Phone: (575) 628-4121

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By

OCT 03 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION**

PROPOSAL NO LATER THAN:

Nov 3, 2013

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1966