District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

JUL **02** 2013 **NMOCD ARTERIA** 

Form C-141 Revised August 8, 2011

NMOGD ARTEMATATE District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

			Relea	se Notific	eation	and Co	rrective <b>A</b>	ction				
nJMW 1319333284						OPERAT	ΓOR		Initia	al Report	Final Report	
Name of Co	mpany	Chevron U	(	Contact I	David A. Pagano	)						
Address 1	5 Smith	Rd., Midlar	7	Telephone No. wk: 575-396-4414X275 cell: 505-787-9816								
Facility Nan	ne TexM	ack BTY	I	Facility Type Oil Production Batteries								
Surface Own	al		Mineral C	Mineral Owner Federal				API No. 30-015-29720) Closest Well Texmack 11-1)				
							Well Textilaek 11-1)					
				Latitude: 32.	853570	/ Longitud	e: -103.843080					
LOCATION OF RELEASE  Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County												
Unit Letter Section Township Range Feet from C 11 17S 31E 990				Feet from the 990			Feet from the 1650	East/West Line West		County Eddy		
			L			i						
				NAT	TURE	OF RELI	EASE					
Type of Relea				Volume of Release 150MSCF/day			Volume Recovered 0 MSCF					
Source of Release Vent						Date and Hour of Occurrence 06/26/13 10:00AM			Date and Hour of Discovery 06/26/13 10:00AM			
Was Immedia	ite Notice (		equired	If YES, To Whom?								
By Whom?				Date and Hour								
Was a Water	course Read	hed?		If YES, Volume Impacting the Watercourse.								
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.*	√A		1						
Describe Cau	se of Probl	em and Reme	dial Action	Γaken.*								
VRU is dowr	at the batte	ery due to the	motor failir	g. Chevron Op	erations	is waiting on	a replacement me	otor and	expect to	have motor i	replaced by 7/10/13.	
Describe Are	a Affected	and Cleanup	Action Take	1.* Loca	ation	us incl	ude: Te	xmak	ill Fe	0,10,11,	15,27,28	
N/A	Describe Area Affected and Cleanup Action Taken.* Locations include: Texmak 11 Fed (0, 11, 15, 27, 28  N/A  Per Email dated 7-2-13											
I hereby certi	fy that the i	nformation g	iven above i	s true and comp	olete to th	ne best of my	knowledge and u	nderstan	d that purs	suant to NM	OCD rules and	
regulations al	ll operators	are required t	o report and	or file certain	release no	otifications a	nd perform correc	tive action	ons for rel	eases which	may endanger	
							arked as "Final R					
							on that pose a three the operator of				iter, human health	
federal, state,				ncc 01 a C-141	report de	oes not renev	the operator or	гезропън	office to the control of the control	omphance v	vitil any other	
						OIL CONSERVATION DIVISION						
Signature:	Daw	id Proce		-								
Printed Name: David A. Pagano						Accepted for record Approved by Environmental Specialist: NMOCD						
Title: Health & Environmental Specialist						Approval Date: Expiration Date:						
E-mail Addre	ess: dpgn	@chevron.co	m			Conditions o		-		Attached	П	
Date: 07/0				5-787-9816	ļ	Like	approv	val	by			
Attach Addi	tional She	ets If Necess	sary				_			2RI	7-1714	
		•					BLM				,	