

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 1333029059

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	SM ENERGY COMPANY 154903	Contact	VICKIE MARTINEZ
Address	3300 N "A" STREET, BLDG 7-200 MIDLAND, TX 79705	Telephone No.	(432)688-1709
Facility Name	PDU 303	Facility Type	INJECTION

Surface Owner	BUREAU OF LAND MANAGEMENT	Mineral Owner	BUREAU OF LAND MANAGEMENT	API No.	30-015-27445
---------------	---------------------------	---------------	---------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	35	19S	29E	1420	NORTH	2500	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	SALTWATER	Volume of Release	81 BBLs	Volume Recovered	55 BBLs
Source of Release	INJECTION LINE	Date and Hour of Occurrence	11/8/13 11:00 AM	Date and Hour of Discovery	11/8/13 11:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM-JAMES AMOS AND NMOCD-MIKE BRATCHER		
By Whom?	RICHARD CHOATE	Date and Hour	11/8/13 11:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

If a Watercourse was Impacted, Describe Fully.*	N/A
---	-----

NOV 20 2013

OCD

Describe Cause of Problem and Remedial Action Taken.*	EXTERNAL CORROSION ON THE BOTTOM SIDE OF A FIBERGLASS TO STEEL TRANSITION CAUSED SPILL.
---	---

Describe Area Affected and Cleanup Action Taken.*	AREA AFFECTED WAS 25' X 250'. VAC TRUCK RECOVERED 55 BBLs. WE WILL TURN OVER TO TETRA TECH FOR ASSESSMENT AND CLEAN UP AS PER BLM REQUEST.
---	--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Vickie Martinez	OIL CONSERVATION DIVISION	
Printed Name: VICKIE MARTINEZ	Approved by Environmental Specialist	Signed By Mike Bratcher
Title: ENGINEER TECH II	Approval Date: NOV 25 2013	Expiration Date:
E-mail Address: VMARTINEZ@SM-ENERGY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/15/2013	Phone: (432)688-1709	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, &
like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

December 25, 2013

ZRP-2075