orm 3160-5	OCD Artesia UNITED STATES					FOI	RM APPROVED	
(August 2007)	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.		
	BORDATO OF EATIND WITH A TODAY EAT					NMLC-029548A		
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter and Abandoned well. Use Form 3160-3 (APD) for such proposals					6. If Indian, Allottee or Tribe Name		
	Abandone	ed well. Use Form	3160-3 (APD)	tor such pro		7 IGIL:4 -CCA/A		_
	SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of V	☐ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No.		
2 No C						COFFEE FEDERAL 19 9. API Well No.		
Z. Name of	e of Operator APACHE CORPORATION <873>					30-015-41044		
3. Address	3b. Phone No.			(include area	Code)	10. Field and Pool or Exploratory Area		
	303 VETERANS AIRPARK LN, #3000 MIDLAND, TX 79705		432-818-1000 / 432-818-1168		1168	CEDAR LAKE; GLORIETA - YESO <96831>		>
4. Location	on of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
III. 2 CEC	2, SEC 8, T17S, R31E, 2350' FNL &450' FWL					EDDY COUNTY,	, NM	
UL: 2, SEC								
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTIC							
TYPE OF	F SUBMISSION TYPE OF ACTION							
							Water Shut-Off	
Notice of I	ntent	Acidize	Deepen		Productio	n (Start/Resume)	☐ Well Integrity ☐ Other	
Subseque		Alter Casing	ion	OR ILLING OPS:				
	Casing Repair New Construction Recomplete CASING & CEMEN							-
Final Aba	ndonment Notice	Convert to Injection	Plug Back Water D			* REPURI		_
					<u></u>	•		
13. Describe F	roposed or Completed (Operation: Clearly state all r	pertinent details, inc	luding estimated s	tarting date of	any proposed work and	approximate duration thereof.	
If the pro	osal is to deepen direct	ional or recomplete horizont	tally, give subsurface	e locations and me	easured and tru	e vertical depths of all	pertinent markers and zones.	
Attached following	the Bond under which the completion of the invol	ne work will be performed o ved operations. If the opera	r provide the Bond I ition results in a mul	No. on file with Bl tiple completion o	LM/BIA. Require recompletion	uired subsequent report i in a new interval, a Fo	s must be filed within 30 days	
testing ha	s been completed. Final	l Abandonment Notices mus	st be filed only after	all requirements, i	including recla	mation, have been com	pleted and the operator has	
	d that the site is ready for BLM-CO-1463	or mai inspection. 09/25/2013 SPUD)			ACCEPTE	D FOD DECODD	
	•					AUDEFIE	D FOR RECORD	ĺ
<u>09/26/2</u> 0		3.375, Hole 17.5, H-			<u>ith:</u>			[
	<u>Lead</u> : 530 sx (1 0 1 0010	ĺ				
1	Circ 251 sks to surface. RECEIVED					NOV	2 4 2013	
	Surface Can Pressure Test: 2000 PSI/30 min NOV 26 2013				113			
[Surface Csg Pressure Test: 2000 PSI/30 min					EUREAU OF	I AND MANACEMENT	
	ONTINUED ON PAGE 2.			ACCD ART	TESIA!	BURSAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE		1
REPORT (ONTINUED ON PAG	E 2.	IMU					
		ng is true and correct.				Acce	Minel dan se e e .	_
Name (Prin	Name (Printed/Typed) MICHELLE COOPER				ILLING TECH		MMBCD 11127120	/3
	• • • • • • • • • • • • • • • • • • • •			Title DRI	ELINO 1201		11/00/120	<u> </u>
Signature	Muhelle	Logsu		Date 10	/24/2013			
		THIS SPAC	E FOR FEDER	RAL OR STA	TE OFFIC	E USE		
Approved by								
Conditions	unroyal if any are attac	ched. Approval of this notice	ce does not warrant	Title			Date	
certify that the	applicant holds legal or	equitable title to those rights						
		nduct operations thereon.						

Title 18 U>S ©. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictilious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

COFFEE FEDERAL #19 - Csg & Cmt End of Well Sundry

A. 09/30/2013 Intermediate Csg 8.625, Hole 11, J-55, 32# set @ 3503' Cmt with:

<u>Lead</u>: 810 sx Class C 65:35 Poz (12.5 wt, 2.13 yld)

Tail: 240 sx Class C w/2% CACL (14.8 wt, 1.33 yld)

Circ 290 sx to surface.

Inter Csg Pressure Test 1500 PSI/30 min-OK

B. <u>10/04/2013</u> Drl 5805'-6412'

C. 10/0 /2013 Production Csg 5.5, Hole 7.875, L-80, 17# set @ 6412' Cmt with:

<u>Lead</u>: 410 sx Class H 65:35 Poz (12.6 wt, 2.0 yld)

Tail: 500 sx Class H 50:50 Poz (14.20 wt, 1.31 yld)

Circ 159 sx to surface.

Prod Csg pressure test 2500 PSI/30 min-OK.

10/05/2013- RR