


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

TMW 1334048783

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Bradley 13 Federal Battery	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner	API No. 30-015-29256
---------------	-----	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	13	25S	29E					Eddy County, NM

Latitude N 32.13175° Longitude W 103.94036°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	45 bbls	Volume Recovered	30 bbls
Source of Release	Pump failure caused tank overflow	Date and Hour of Occurrence	11/11/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Chancey Summers	Date and Hour	11/12/13 @ 3:00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Pump failure caused a tank to overflow and leak 45 bbls of produced water onto the ground. 30 bbls of produced water were recovered via vacuum truck and the pump was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 25' x 25' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chancey Summers

Approved by Environmental Specialist:

Signed By

Title: HES Specialist

Approval Date:

DEC 04 2013

Expiration Date:

E-mail Address: Chancey.Summers@oxy.com

Conditions of Approval:

Date: 11/25/13

Phone: (575) 397-8216

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

Attached ☐

* Attach Additional Sheets If Necessary

January 6, 2014

2RP-2096