

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

DEC 04 2013

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

50 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW1334333986

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Grave Digger State Com #003	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-39151
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	02	20S	25E					Eddy

Latitude 32.609044

Longitude 104.452946

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5bbls of oil 10bbls of produced water	Volume Recovered	3bbls of oil 6bbls of produced water
Source of Release	Fire tube on heater treater	Date and Hour of Occurrence	10-26-2013	Date and Hour of Discovery	10-26-2013 1:30pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the fire tube on the heater treater. Replaced the fire tube.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 15bbls were released from the heater and we were able to recover 9bbls with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility. Fresh gravel has been added as necessary. The facility has been returned to its prior condition					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: *Robert Grubbs Jr.*  
Printed Name: Robert Grubbs Jr.  
Title: Senior Environmental Coordinator  
E-mail Address: rgrubbs@concho.com  
Date: 11-06-2013 Phone: 432-661-6601

Approved by District Supervisor: Signed By *White*

Approval Date: DEC 09 2013

Expiration Date:

Conditions of Approval:  
Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION

Attached ☐

PROPOSAL NO LATER THAN:

*January 9, 2013*

*2RP-2101*

\* Attach Additional Sheets If Necessary