


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*njm* *W1334648160* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #101	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-26105

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	05	26S	28E					Eddy

Latitude 32.07351

Longitude 104.1067

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	85bbls	Volume Recovered	35bbls
Source of Release	3" steel line	Date and Hour of Occurrence	11-26-2013	Date and Hour of Discovery	11-26-2013 08:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	11-27-2013 09:45am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 3" steel line between the H-pump and the well head corroded due to corrosion.

Describe Area Affected and Cleanup Action Taken.\*

Initially 85bbls of produced water were released from a steel line that had developed a hole going from the H- pump to the well. We were able to recover 35bbls with a vacuum truck. The release was contained on the location. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Robert Grubbs Jr.</i>	Approved by District Supervisor: <i>Mike Bratcher</i>	
Printed Name: Robert Grubbs Jr.	Signed By: <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator	Approval Date: DEC 12 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: January 12, 2013	Attached <input type="checkbox"/>
Date: 12-11-2013 Phone: 432-661-6601		

\* Attach Additional Sheets If Necessary

2RP-2109