

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

DEC 11 2013

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

*TM* 1334728810 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Central Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-27764

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	24	17S	29E					Eddy

Latitude 32.819

Longitude 104.025

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	12bbls	Volume Recovered	10bbls
Source of Release	Steal breaded hose	Date and Hour of Occurrence	11-30-2013	Date and Hour of Discovery	11-30-2013 07:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Steal breaded hose failed on discharged pressure on murphy. Replace hose.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 12bbls of produced water were released due to a failed breaded hose on murphy. We were able to recover 10bbls of produced water with a vacuum truck. All free fluid has been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a work plan to the BLM/NMOCD for approval prior to any significant remediation work					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: <i>Robert Grubbs Jr.</i>	Approved by District Supervisor: Signed By <i>Mike Brumley</i>	
Printed Name: Robert Grubbs Jr.	DEC 13 2013	Expiration Date:
Title: Senior Environmental Coordinator	Approval Date:	
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12-11-2013 Phone: 432-661-6601	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

\* Attach Additional Sheets If Necessary

January 13, 2013

2RP-2112