

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

DEC 12 2013

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimaxex Energy 215099	Contact Christine Alderman
Address 600 N Marienfeld Midland, Tx 79701	Telephone No. 432-853-7059
Facility Name DaVinci 7-4	Facility Type production battery

Surface Owner BLM	Mineral Owner	API No. 30-015-41418
-------------------	---------------	----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	7	025-S	027-E	50	N	2435	W	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10BBLs	Volume Recovered 0
Source of Release water transfer line	Date and Hour of Occurrence 11/26/2013	Date and Hour of Discovery 11/26/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Van Curen, Mike Brachard	
By Whom? Christine Alderman	Date and Hour 11/26/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

A water transfer line in the pasture just off location developed a hole. Upon discovery, a clamp was placed on the line.

Describe Area Affected and Cleanup Action Taken.\*

Pasture land, approximately 10' x 50'. Talon was contacted to collect samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman		Approved by Environmental Specialist: Signed By <u>Mike Brachard</u>	
Title: EHS compliance Coordinator		Approval Date: DEC 13 2013	Expiration Date:
E-mail Address: calderman@cimaxex.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/12/13 Phone: 432-853-7059		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

\* Attach Additional Sheets If Necessary

January 13, 2013

2RP-2114