District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

	The state of the same of the s						
RE	CEIVE	Ü					

DEC 16 2013 Revised October 10, 2003

NMOCD Albanic Ornics to appropriate
With Rule 116 on back
side of form

	•			ა	anta F	e, NM 8/5	005					
\	\cap		Rel	ease Notifi	catio	n and Co	orrective A	ction				
MCn	1133	52564	51	•		OPERA'	ГOR	■ Initi	al Report		Final Repor	
Name of Company COG OPERATING LLC 22913					1137	Contact Robert McNeill						
Address 600 West Illinois Avenue, Midland, TX 79701						Telephone No. 432-230-0077						
Facility Name Loco Hills SWD 33 #004						Facility Type Tank Battery						
Surface Owner Federal Mineral Owne					Owner	Lease No. (API#) 30-015-37					5-37269	
	•	,		LOC	ATIO	N OF RE	LEASE			•		
Unit Letter	Section 33	Township 17S	Range 30E	Feet from the	North	South Line	Feet from the	East/West Line	County	Eddy		
	1	:		Latitude 32.7	78607	Longi	tude 103.97054	<u> </u>	 			
						•						
Typu of Polo	ona Deculus		····	NA:	IUKE	OF REL			7	01.1.1		
Type of Kele	Type of Release Produced water					Volume of Release 10bbls Volume Recovered 9				YODIS		
Source of Release Steel flowline						Date and F	lour of Occurrenc	Date and Hour of Discovery 12-05-2013 08:00am				
Was Immediate Notice Given? ☐ Yes ☒ No ☐ Not Required					.equired	If YES, To Whom?						
By Whom?					<u> </u>	Date and Hour						
Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse.							
· 🔲 Yes 🗵 No												
If a Watercou	irse was Im	pacted, Descri	be Fully.		<u></u>							
Describe Cau	se of Probl	em and Remed	dial Action	Taken.*			:	<u> </u>				
A steel flow	ine develor	ped ⁱ a hole due	to corrosi	on. Replaced the	steel line	e.						
Describe Are	a Affected	and Cleanup A	etion Tak	cn.*								
Initially 10bb have been rec	ls of productive overed. Co	ced water were ncho will have	e released c the spill	A hole develope	elineate	any possible	contamination fro	ecover 9bbls with a m the release and v	vacuum tru we will pres	ick. Ali ent a re	free fluids mediation	
regulations all public health should their o or the enviror	l operators or the envir perations h ment. In a	are required to ronment. The ave failed to a	report an acceptance dequately CD accep	d/or file certain r e of a C-141 repo investigate and r	release no ort by the remediate	otifications ar 2 NMOCD ma 2 contamination	nd perform correct arked as "Final Re on that pose a threet the operator of r	nderstand that purs tive actions for rele epon!" does not reli eat to ground water responsibility for co	eases which eve the ope , surface wr ompliance v	may en rator of iter, hui vith any	idanger Tiability man health	
						OIL CONSERVATION DIVISION						

Attach Additional Sheets If Necessary

Robert Grubbs Jr.

Senior Environmental Coordinator

432-661-6601

rgrubbs@concho.com

Signature:

Title:

Printed Name:

E-mail Address:

Date: 12-11-2013 -

January 18,2013

Approved by District Supervisor: Signed By

Remediation per OCD Rule & Guidelines, &

like approval by BLM. SUBMIT REMEDIATION

18 2013

Expiration Date:

Approval Date:

Conditions of Approval:

2RP-2116

Attached [