District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Sama Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

DEC 16 2013

Form C-141 d October 10, 2003

NMOCD ARTES Agies to appropriate Hice in accordance with Rule 116 on back side of form

Release Notification and Corrective Action													
NM 1335337210							OPERATOR			🛭 Initial Report 🔀 Final Report			
Name of Co	mpany			G LLC 2291	37	Contact	·	Rob	n McNeill				
							Telephone No. 432-230-0077						
Facility Nar	ne	Birdseye	32 State	#004H		Facility Type Tank Battery							
Surface Owner State . Mineral Owner									Lease	No. (API#)	30-01:	5-39387	
LOCATION OF RELEASE													
Unit Letter M	Section 32	Township 19S	Range 31E	Feet from the	North/	South Line	Feet from	n the E	ast/West Line	County	Eddy		
( ()		193	316	Latitude 32.6	1048	Longi	ude 103.	.89886			eddy		
NATURE OF RELEASE													
Type of Release Oil and produced water						Volume of				Recovered 10bbls of oil 8bbls of produced water			
Source of Release Gasket on separator failed							e and Hour of Occurrence Date ar			d Hour of Discovery 013 09:30am			
Was Immediate Notice Given?						If YES, To Whom?  Mike Bratcher - NMOCD							
By Whom? Michelle Mullins						Date and Hour 12-06-2013 07:33am							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
Back pressure on the separator caused the gasket to fail. Replace the gasket and watch the back pressure.													
Describe Area Affected and Cleanup Action Taken.*													
Initially 15bbls of oil and 10bbls of produced water were released from the separator. We were able to recover 10bbls of oil and 8bbls of produced water with a vacuum truck. The spill was contained inside the fined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the													
liner has been steam cleaned and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
,						OIL CONSERVATION DIVISION							
Signature:	Te	21+1	Low	1						A.			
Printed Name	Printed Name: Robert Grubbs Jr.						Approved by District Supervisor: Signed By Mile Examples						
Title:	S	enior Environ	mental Co	ordinator		Approval Date	JEC 1	9 2013	Expiration	Date: .			

\* Attach Additional Sheets If Necessary

12-11-2013

rgrubbs@concho.com

432-661-6601

E-mail Address:

2RP-212

Attached [

Conditions of Approval: