

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-05135
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lee Whitman A
8. Well Number #1
9. OGRID Number
10. Pool name or Wildcat Denton (Devonian)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Americo Energy Resources, LLC

3. Address of Operator

7575 San Felipe, Suite 200, Houston, TX 77063

4. Well Location

Unit Letter **G** : **1980** feet from the **North** line and **1980** feet from the **East** line
Section **26** Township **14S** Range **37E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3800 GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: **Mechanical Integrity Test** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Subsequent Report of workover.

Informed "OCD" Mr. Gonzales.

Note: 1998 Chevron reported tight spot in 7" casing at 7378'. 5.6" gauge did not go through.

- Installed and test 4 anchors on location and cleaned up the area.
- level of and remove tall weeds and push aside.
- 9/23/06 MIRU E.line unit.GIH w/1.25" bar to 12325'. Pooh . GIH w/3-1/8" bar went through-tight spot.
- GIH with 5.76" gauge ring, tag bad spot in casing at 7362'. Pooh and rig down wire line unit. -
- 10/5/06-10/11/06 MIRU workover unit, spot pump and tank. N/D tree, N/U and checked BOP's.
- GIH w/4-3/4" bit, 2 jts 2-3/8" and packer. Set packer at 7309' & tested tools did not hold. Pooh lay down pkr.
- GIH w/6-1/8" bit & scraper cleaned up casing to 7362'. Pooh & lay down bit & scraper.
- TIH w/7" RT.Bridge plug and packer. Set Bridge plug at 7318'. PU & tested plug 550# for 10 mts held OK.
- Re-set packer at various depth above bridge plug & tested 7" casing 500 psi to surface held OK for 30 minutes.
- Pooh & lay down work string. Laid down packer and RT.Bridge plug. N/D BOP's and installed Flange on the well.
- Closed well in. Pending well evaluation and AFE approval.

Chart attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE *Robert M. Gray* TITLE Land Manager DATE 10/16/06

Type or print name Robert M. Gray E-mail address: don.gray@americoenergy.com Telephone No. 713-984-9700

For State Use Only

APPROVED BY: *Chris Williams* TITLE DISTRICT SUPERVISOR/GENERAL MANAGER DATE OCT 23 2006

Conditions of Approval (if any):

Complete work by 1/22/07

