Form 3160-5 (August 2007)

OCD-ARTESIA

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

NMNM-100561

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No Oil Well Gas Well Other STRAWBERRY 7 FEDERAL #3 2. Name of Operator 9. API Well No. 30-015-37171 DEVON ENERGY PRODUCTION COMPANY LP 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 3a. Address HACKBERRY; BONE SPRINGS, NORTH 575-748-3371 PO BOX 250, ARTESIA, NM 88211 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State EDDY COUNTY, NM UNIT D, 330' FNL & 660' FWL, SEC 7, T19S, R31E 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat ✓ Reclamation Well Integrity New Construction Casing Repair Recomplete Other ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) NO WHEED 1/8/9014 RE: 3162.4 (NM-080) NMNM100561 BLM LETTER DATED 9/7/2010 AFTER INTERIM RECLAMATION OF THE ABOVE WELL, THE BLM INSPECTED THIS WELL ON 9/5/2010. IT WAS RECOMMENDED TO "REDISTRIBUTE THE MATERIAL ON THE EAST SIDE OF THE LOCATION TO FILL IN THE CUT AND UTILIZE THE WOODY DEBRIS AS MULCH." THIS WORK HAS BEEN COMPLETED AND DEVON REQUESTS ANOTHER INSPECTION. JAN **08** 2014 2014 NYOCD ARTESIA 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **XU OF LAND MANAGEMENT** CARLSBAD FIELD OFFICE ROGER HERNANDEZ (by D. Menoud) Title PRODUCTION FOREMAN Date 11/12/2010 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

entitle the applicant to conduct operations thereon.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, NM 88220-6292 SEP 0 7 2010 ARTESIA, N.M.

In Reply Refer To: 3162.4 (NM-080) NMNM100561

September 7, 2010

Devon Energy Production Company LP P. O. Box 250 Artesia, NM 88210

Re:

Dean suploant

NMNM100561; Strawberry 7 Federal 3

330' FNL & 660' FWL, Section 7, T. 19 S. - R. 31 E.

Eddy County, New Mexico

Ladies and Gentlemen:

On September 5, 2010 the Bureau of Land Management (BLM) completed a field examination of the above referenced well. The well has recently undergone interim reclamation. Overall the reclamation looks good. The objective would be to return as much of the location to a condition that the restoration is complete and will not have to be touched at the final reclamation stage. This location could have achieved the objectives.

The west side of the location is on the downhill slope. The caliche was removed and the area sloped, but not to the natural slope. The excess material could have been moved to the east side of the location where there is a cut. This area had the caliche remove and was ripped and seeded without addressing the cut. Above the cut is pushed up soils and vegetation debris from the initial location clearance. This material could be redistributed over the east portion and utilized as mulch, helping to stabilize the slope.

We currently have good revegetation occurring over all reclamation. However, I would like to redistribute the material on the east side of the location to fill in the cut and utilize the woody debris as mulch.

If there are any questions please call Jim Amos, Supervisory Environmental Protection Specialist, at (575) 234-5909.

Sincerely,

James A. Amos

Supervisory Environmental

amo Q. amo

Protection Specialist