Form 3160-5 (August 2007)

OCD Artesia

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMLC029426A

SUNDRY	NMLC029426A								
Do not use thi abandoned we	6. If Indian, Allott	ee or Tribe Name							
SUBMIT IN TRI	PLICATE - Other instruc	ctions on re	verse side.		7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well Gas Well Oth	8. Well Name and No. H E WEST A 033								
2. Name of Operator LINN OPERATING INC	9. API Well No. - 30-015-28325								
3a. Address 600 TRAVIS STREET, SUITE HOUSTON, TX 77002	5100	3b. Phone N Ph: 281-8	o. (include area co 40-4272	de)	10. Field and Pool, or Exploratory GRAYBURG JACKSON;SR-Q-G-S				
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description)			11., County or Pari	sh, and State			
Sec 4 T17S R31E Mer NMP S 32.859920 N Lat, 103.873850		L			EDDÝ COUN	NTY COUNTY, NM			
12. CHECK APPE	OPRIATE BOX(ES) TO	O INDICATI	E NATURE O	F NOTICE, RE	EPORT, OR OTI	HER DATA			
TYPE OF SUBMISSION		TYPE	OF ACTION						
Notice of Intent	☐ Acidize	□ De	epen .	□ Producti	on (Start/Resume)	☐ Water Shut-Off			
☐ Subsequent Report	☐ Alter Casing	_	cture Treat	☐ Reclama		■ Well Integrity .			
_ , ,	☐ Casing Repair		w Construction	□ Recomp		Other			
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection		g and Abandon g Back		⊠ Temporarily Abandon				
determined that the site is ready for five LINN WOULD LIKE APPROVE PRESERVE IT FOR FUTURE PROPOSED TA PROCEDURE 1. TEST RIG ANCHORS PRICES MIRU. CHECK ALL PRESS	AL TO TA THE H E WES SAN ANDRES, GRAYBI ES: DR TO RIGGING UP.	URG AND S	EVEN RIVERS	RECOMPLET SEE	ION POTENTIAL ATTACHE	L.			
3. BLEED OFF ANY PRESSU CONTACT ENGINEER F PRE	RE AS NECESSARY. IF	WELL IS FI	OWING, FLOY NEEDS TO BE	W BACK TO FI E KILLED.	RAC TANK OR \	/AC TRUCK.			
Accepted for record CED MMOCD 3/31/14	SUBJECT TO L APPROVAL BY S	IKE TATE		•		RECEIVED			
14. I hereby certify that the foregoing is Name(Printed/Typed) TERRY B	Electronic Submission #2	PERATING II	C, sent to the by JERRY BLA	Carlsbad	2014 ()	MAR 3 1 2014 MOCD ARTES			
•									
Signature (Electronic S		, 	Date 03/21						
	THIS SPACE FO	R FEDER	L OR STAT	E OFFICEDUS	ROVED				
Approved By My	Shis		Title		TOVED	Date .			
Conditions of approval, if any are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to thourights in the ct operations thereon.	subject lease	Office		2 4 2014				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	J.S.C. Section 1212, make it a tatements or representations as	crime for any p to any matter w	erson knowingly a ithin its jurisdictic	nd BUKEKU OF A	KANDOMARPARTEMI ND EIFLD DEELCE	Pyragency of the United			

Additional data for EC transaction #239572 that would not fit on the form

- 32. Additional remarks, continued
- 4. NU 5000# BOP
- 5. UNSET TAC AND POOH
- 6. RIH W/ CIBP AND SET AT 3200°, PRESSURE UP TO 500# AND CHECK FOR LEAKS
- 7. PUMP 25 SXS CLASS C CMT
- 8. WOC AND TAG
- 9. PRESSURE UP ON CSG TO 500# FOR 30 MIN AND CHECK FOR LEAKS, CIRC PKR FLUID
- 10. POOH LD TBG
- 11. RDMO
- 12. NOTIFY OCD AND PERFORM MIT

Current Well Schematic (NM)

LINN Energy, Well Name: WEST HEA 33

l								
APIJUWI	Field Name	County	State/Pr	ray Section	Township	Range	Survey	Élock
3001528325	PB-GRAYBURG	Eddy	NM	4	017-S	031-E		·
Ground Elevation (ft) Orig KB	Elev (ft) KB-Grd (ft)	Inibal Spud Date	Rig Release Date	TD Date	Latituda (*)		Longitude (*)	Operated?
3,917.00		2/7/1995		2/13/1995				Yes

	,								
4.211.0 4.254.1	Production Casing Cement, 0.0-4,284.0; 2/13/1995; 1200exs cmt, circ to surface TD - Griginal Hole; 4/284.0	·		· · · · · · · · · · · · · · · · · · ·				•	
4,194.9 4,200.1	Perforated; 4,200.0-4,211.0; 4 holes, 4200, 05, 08 11 -5 1/2; Production: Casing; 4,284.0							-	
4,169.9	Perforated: 4.170.0-4,195.0; 8 holes, 4170, 73, 84, 90, 93, 96	мил тор Берил (лкв	>)	3,97		реріл (пкн)		4,2	211.0
4,137.1 4,166.0	Perforated: 4,137.0-4,166.0; 5 holes, 4137, 39, 56, 61, 66	Acidize w/ 275		% HCl acid		Depth (ftKB)			
4,100.1	4190	Acidizing on 3	3/17/199	5 00:00 意識	The Paris of the P		YAL ES		E E
4 078.1	Perforated: 4,078.0-4,100.0; 3 holes, 4078, 82,	3/16/1995	4,200.	4,211	0 4 holes.	4200, 05,	08, 11		(مقالته د د د د
4,034.1	Perforated: 4,034,0-4,057.0; 4 holes, 4034, 41, 46, 57	1	第4,170.	1	0 6 holes				· · · · · · · · · · · · · ·
3,974.1	Perforated; 3.974.0; 1 hole	3/16/1995 3/16/1995	4,137.	0 4.100 4.166	0 5 holes		177		
3,950.1	C19210.950.0 577770111	3/16/1995	4,034.0		0 4 holes,	4034, 41,	46, 57		
3,699.9	3901	3/16/1995	3,974.	1		2010, 00,		X 3 1	
3,678.0	Perforated; 3,878,0-3 901,0, 3 holes, 3878, 99_	3/20/1995 3/20/1995	3,853.0 3,878.0		0 3 holes 0 3 holes	3853,56; 3878, 99,	ف واست من الله	类。	7,362 347 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12.00 12
3,853.0 3,858.9	Perforated; 3,853,0-3,859,0, 3 holes, 3853, 56, 59	3/20/1995	3,810. 3,853.		0 4 holes			سمسان دیمند بالی	ورونسان
3,635.0	35	1		0 3:789				Market Co	70 /85
3,789,0 3,610.0	Periorated; 3,810,0-3,835.0, 4 holes, 3810, 14, 33	3/20/1995 3/20/1995	3,679.0 3,730.0		0 1 hole) 0 3 holes			16. 23.	
3,752.0	Perforated: 3,752.0-3,789.0; 4 holes, 3752, 56, 68,	3/20/1995	3,623.	3,628	0 2 holes,	3623, 28			تدريق مناد واست ا
3,747.0	Perforated; 3,730,0-3,747,0; 3 holes, 3730, 32, 47	1	3,521.1 3,589.1	1	0 4 holes			3]"[]	- PM- 1
3,692.9		4/11/1995 3/20/1995	∏3,444; 3,521.		0 4 holes	The second second		1	9
3,679.1	Perforated; 3,679,0; 1 hole	4/11/1995	3,425.	3,438	0 4 holes.	3425, 27,	36, 38		عسنس
3,662.1 3,667.3		4/11/1995 4/11/1995紀 紀	3,364. 3,407.		0 4 holes, 0 2 holes,		-	1. 19 m	
3,658.1		4/11/19955 B		0 13,353	0 5 holes 0 4 holes	The second second		53.	
3,626.0		4/11/1995	3,275.	0 3,279	.0 3 holes,	3275, 77,	79	1.1.0	
3,625.6	Perforated, 3,623.0-3,628.0, 2 holes, 3623, 28	Rerforations@		والمستخرجين والمستخرجين			, je		
3-505.3 3,623.0		Description B	3,950.	Run Date .0 5/23/201	Comment 1 Set CIB	P w/ 8' out	on it 12	5 @ 39	50'
3,603.0	3603	Other In Hole						en en	
3,588.9	Periorated, 3,589.0-3 603.0, 4 holes, 3589, 93, 96.	& 1/4 #/sk D29 Celloflake							
3.521.0 3.564.0	Perforated, 3,521,0-3,564.0; 3 holes, 3521, 45, 64	Comment Lead slurry 850							
3,493.4		Production Car Cement	ising	0.0	4,284	surface		IIG 10	
3,443,9 3,451,9	Perforated; 3,444,0-3 462.0, 4 holes, 3444, 51, 58, 62	Description	To	p Depth (RKB)		Common		ire to	
3,438.0	## Penorated, 3,425,0-3,436,0,4 notes, 3425, 21, 30,	Lead slurry 16: w/ 200sx Class			5% D-20 +	1/4 #/sk D	-29 + 29	S-1, T	ail
3,40£.1 3,424.9	Perforated, 3,425,0-3,438,0,4 holes, 3425, 27, 30,	Cement Comment							
3,407,2	Perforated; 3,407,0-3 409.0, 2 holes, 3407, 09	Description Surface Casing		op Depth (fiKB) 0.0		Comman 365sxs		c to suri	face
3,383.8 3,383.9	Perforaled; 3,364.0-3 381.0, 4 holes, 3364, 70, 79.	Cement Stage	es 📜		Processor Carrier Carrier		Aug II	And Adding	Y.T.
3 353,0	39, 53	Run Date 2/13/199		Casing Descript	ion ·	Set Depth (fit		D (in)	5 1
3,278,9 3,315.0	Perforated; 3,315.0-3,353.0; 5 holes, 3315, 21, 37,	Run Date 2/7/1999		Casing Descrip	ion	Set Depth (fit		D (in)	8 5
3,274.9	Perforated, 3,275,0-3,279.0; 3 holes, 3275, 77, 79	4,284.0 Tot			7.5 11.12.45	11.	W 9 11		
1,222.8		(Depth (ftKB)		Spanning American	Annota	ition Care			
· s _. 795,9	Production; 7.7(8; 60), 0-4.284.9	Start Date 2/13/1995		n Description Juction		S	นอ (เก) 7 7	Act Bin	m (ftK ,284
25.9 601.0	8 5/8; Surface; Casing; 601,0 Surface Casing Cement; 0,0-601,0; 2/7/1995; 365sxs cmt, circ to surface	Start Date 2/7/1995	Section Surfa	n Description , 308		S	ize (in) 12 1,	Act Bin	m (nK 601
00	Surface: 12 1/4; 0,0-601.0	1,299.0 FSL Wellbore Sec		5.0 FWL		35.712" N	103	52' 25.	.00
			1 0 67	E OLDAN I	006 241	94 94 90 KI	400	COLOR	004

LIZATAT

FIN	N)		Cu	rrent We	ell Sch	nematic	(MM)				
Enen Well I	w Name: WEST I	-l E A 33									
APVUWI		ald Name	County		State/Prov	Section	Township	Range	Survey	Block	
300152	28325 Place Place	B-GRAYBURG	Eddy Initial Spud Date	Rig Release	NM Date IT	4 D Date	017-S Latitude (*)	031-E	Longitude (*)		Operated?
Ground	3,917.00	(ii) KBOIG (ii)	2/7/1995	IVIS IVEESSO	Ua.u	2/13/1995	Espines ()		Congrada ()		Yes
اون من ساسده		Original Hole, 3/13/201ر					on'3/19/199	5.00:00			
MD (fikB)	a :	Vertical sch	ematic (actual)@@r@\@	METAL WALLER	Warners and a		0.000 pale à	1 ± 76 000# 3/)/40 Brady sand	1 + 34 000#	roein
0.0	XX XX (1) 112		Surface: 12.1/4; 0.0-50			coated sar) .	1140 Diady Sain	24,000F	16211
25.9 601.0		T	8 5/8; Surface; Casing. Surface Casing Cemer	nt; 0.0-601,0, 2/7	/1995;	Min Yep Depu	(nKB)	3,974.0	Max Bim Depin (fil	(B)	4,211.0
1,795.9			365sxs cmt, circ to sur			Acidizing	on 3/20/199				7,217.0
3,222.5	20		-Production: 7 7/8; 601.	0-4.284.0		Comment	4850 gals 15				
3,225,4	2 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7					Min Top Depth		noi aciu.	Max Bim Dopin (file	(8)	
3,274.9	N. W.		Perforated, 3,275.0-3,2	279.0; 3 holes, 32	275, 77, 79		******	3,521.0			3,901.0
3,278, 0 3,315,0			Perforated; 3,315,0-3,0	153 O: 6 holes 31		Comment	"on"3/28/199	5.00:00			
3,353,0			39, 53	100.0, 0 110/03, 00	,13, 21, 31,	4 .		el + 50,750# 20)/40 Brady San o	1 + 16,540#	resin
3,363,6			Perforated, 3,364.0-3,3	381,0; 4 holes, 33	364, 70, 79,	Coaled sar			Max Bim Depth (filk	(B)	
3,350.9			81					3,521,0			3,901.0
3,407.2	W. I		-Perforated; 3,407,0-3,4	109.0; 2 holes, 34	107, 09	Comment	on 4/12/199	5 00:00 <u>F</u>		3342	
3,424.9			Perforated; 3,425,0-3,4	138.0: 4 holes 34	125, 27, 36,	Acidize w/	2700 gals 15	% HCI acid.			
3,438,0			38			Min Top Depth	(µKB)	3,275.0	Max Bim Depth (Rix	(B)	3,462. 0
3,443,0			Perforated, 3,444.0-3,4	162,0; 4 holes, 34	144, 51, 58.		on 6/5/1998	00:00		of the later of the state of th	
3,481,0 3,493.4			02			Comment Acidize w/	2150 gals 15	% HCLacid +	1000# rock salt.		
3,521.0	1					Min Top Depth			Max Bim Depth (file		
3,564 0			Perforated, 3,521,0-3,5	64.0, 3 holes, 3:	21, 45, 64	Acidizina	nn'C/E/4000	3,679.0 00:00 <i>[</i>	·		4,211,0
3,588,2			Perforated; 3,589,0-3,6	603.0; 4 holes, 35	89, 93, 96,	Comment	016 0101 1930	00.00	in a second		- Andrews
3,503.0	1778		3603			Acidize w/		% HCl acid +	1200# rock salt. Max Bun Depin (fix		
3,605,3 3,623.0							(MIND)	3,275.0			3,628.0
3,626.6		R CHI	Perforated; 3,623.0-3,6	328.0; 2 holes 36	323, 28	Run Date	Pull Date	Tubing Da	Cantion		Set Doptn (RKB)
3,528.0						7/3/2013	3	Tubing	- Production		3,693.0
3,643,4 3,658,1						Tubing	Des		03 2 7/8 2.	(h)0 /⊏2Grad 441 J-55	6.50
3,562.1						Anchor/cat	cher	{2.75		441,	
3,667,3				•		Tubing	٠	379.88	many and the second bearing	441 J-55	6.50
3,678,1			Perforated, 3,679 D; 1 I	note		Pump barr	أساعت وسيد بينت وسأشارك	721:10	1 27/8		
3,692.9						Seating Ni	*	31.50	. 1 1	441 J-55	6.50
3,747.0	1423		Perforated; 3,730.0-3,7	'47.0; 3 holes, 37	30, 32, 47	Reiforated	(r apilia)	(4:00	1. 12.7/8		
3.752.0			_Perforated, 3,752.0-3,7	89.0; 4 holes, 37	52. 56, 68.	mud joint		31.00	1 27/8	<u> </u>	المتسنسة السنة
3,769.0			09			Bull Plug	السينف		M: []2,7/8		
3,810.0 3,835.0			_Perforated; 3,810,0-3,8 35	35.0; 4 holes, 38	10, 14, 33,	RodiString Run Date	Puli Date	Rod Desc	a Lilia	18	el Depth (RKB)
3,853.0			-Perforated, 3,853,0-3,8	60 n: 1 balas 20	E1 EC E0	7/4/2013	3	Rod			3,667.3
1,858.9			— i eriorateu, 3,853,0-3,8	J.J.O. J HO(65, 38	JJ. JQ, 58		od 1 1/4 X 1			(in) □ Grade 1/4	C) GWI (b/m)t)
3.876.0			_Perforaled; 3,878 0-3,9 3901	01.0; 3 holes : 38	78, 99,	1/2 liner X					
3,899.9						Harris and the Contract	1	شبها الانتكاما البيد	المحالة	7/8 D)	2.22
3,950.1			CIBP: 3.950.0: 5/23/70	111		Sucker Ro		68	1,697,30	3/4 D	1.63
3,974,1			Perforated; 3 974 0; 1 h	ole		Sinker, Bar, Tubing Pur		6	24.00	1/2 3/4 D	-4
4,034,1			Perforated; 4,034,0-4,0 57	57,0; 4 hales, 40	34, 41, 46,	Tubing Ful	ייף		27.00	3/4 D	1.50
4,057.1 4,078,1	I KWI		Device to the second se	60 ft. 2 belee - 40	מה מד						
4,100,1	1400		Perforated; 4,078 0-4,1 4100	vulų; a noles, 40	110, 64,						
4,137.1	 		Perforated; 4,137,0-4,1	66 0; 5 holes, 4 l	37, 39, 56,						
4,165.0			ີ61, 65 ຼ Parloraled; 4,170.0-4,1	95,0; 6 holes, 41	70, 73, 84,						
4,159.9 4,194.9			90, 93, 96 Perforaled; 4,200.0-4,2								
4,200,1			「11 ⊢5 1/2; Production; Casi	ng: 4.284.0							
4,211,0	4 24		Production Casing Cem 2/13/1995: 1200sxs cm	ient: 0.0-4.284.0	;						
	Fig. Lauren	maine i Karl	ITA Named Vale 450	777		1					


4,284.1

LINN Energy

Proposed TA (NM)

Well Name: WESTHEA33

, ,	Field Name PB-GRA	YBURG	County Eddy		State/Prov NM	.		Township 017-S	Range 031-E	Survey	Block	
Ground Elevation (ft) Orig KB (3,917.00)	lev (ft)	KB-Grd (ft)	Initial Spud Date 2/7/1995	Rig Release (Date TE	Date 2/1	3/1995	Latitude (*)		Longitude (*)		Operated? Yes



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 6 months ending 9/24/2014 subject to conditions of approval. JDB

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram
 with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- •4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

H E West A #33

- 1. Well may be approved to be TA/SI for a period of 6 months or until 9/24/2014 after successful MIT and subsequent report is submitted. CIBP to be set at 3220'
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 9/24/2014.