Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		• • • •	Form C-103 May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-05284 5. Indicate Type of	flesse	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE _	FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	District IV 220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas LC029395B	Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Turner B		
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other Water Injection Well		8. Well Number	# 12	
2. Name of Operator	RECEIVED			9. OGRID Number	
Merit Energy Company 3. Address of Operator	OCT 1 1 2005		14591 10 Pool name or V	14591 10. Pool name or Wildcat	
13727 Noel Road, Suite 500, Da	allas, Texas, 75240	OCD-ARTEGIA	ľ	JACKSON;SR-Q-G-SA	
4. Well Location					
	om the SOUTH line and 660				
Section 20	Township 175		NMPM	County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3626' GR Pit or Below-grade Tank Application or Closure					
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water					
Pit Liner Thickness: mil	Below-Grade Tank: Volum	ebbls; C	onstruction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	TENTION TO: PLUG AND ABANDON [CHANGE PLANS [MULTIPLE COMPL [REMEDIAL WOR COMMENCE DR	ILLING OPNS. P	ORT OF: ALTERING CASING O AND A	
OTHER:	Г	OTHER:		M	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
TURNER B # 12 WATER INJECTION WELL FAILED ITS IMIT ON 4/28/2005, BECAUSE NO BRADENHEAD CONNECTION WAS VISIBLE.					
THE BRADENHEAD CONNECTION WAS UNCOVERED & A MIT TEST WAS PERFORMED ON 9/20/2005 TO VERIFY WELLBORE INTEGRITY. THE CHART RECORDING THIS SUCCESSFUL TEST IS INCLUDED WITH THIS DOCUMENT.					
Accepted for record - NMOCD					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelimes , a general permit or an (attached) alternative OCD-approved plan .					
SIGNATURE Sang M. Type or print name LARRY M.	Andus TIT	LE. S. Reg. an	slipt D	DATE 10/5/05	
Type or print name LARRY YN. For State Use Only	SANDERS E-m	naiil address:		ohone No. 972-628 -	
APPROVED BY: Conditions of Approval (if any):	TIT	LE	D	PATE	

