

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 14 2014

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Burch Keely Unit #205	Facility Type	Tank Battery

Surface Federal	Mineral Owner	Lease No. (API#) 30-015-031333
-----------------	---------------	--------------------------------

LOCATION OF RELEASE

03133

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Q	26	17S	E					Eddy

29E Latitude 32.80008 Longitude 104.04331

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 50bbls	Volume Recovered 40bbls
Source of Release Water line	Date and Hour of Occurrence 01-02-2014 2014	Date and Hour of Discovery 01-02-2014 11:30am 2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 01-03-2014 09:13am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Pipeline crew hit water line. Replace the section of pipe.

Describe Area Affected and Cleanup Action Taken.\*

Initially 50bbls of produced water were released when a pipeline crew hit our line. We were able to recover 40bbls with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator		Approval Date: JAN 29 2014	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: March 1, 2014	
Date: 01-14-2014 Phone: 432-661-6601		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-2171