


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nMLB/406342981

OPERATOR

☒ Initial Report ☐ Final Report

| | | |
|--|------------------------------|--------------------|
| Name of Company Burnett Oil Co. Inc. | Contact Shawna Matthews | |
| Address P.O. Box 188, Loco Hills, NM 88255 | Telephone No. (575) 322-7213 | |
| Facility Name Gissler B-3-1 | Facility Type Tank Battery | |
| Surface Owner BLM | Mineral Owner | API No. 3001504120 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| B | 11 | 17S | 30E | 866 | FNL | 1847 | FEL | Eddy |

Latitude 32.854395 Longitude -103.939889

NATURE OF RELEASE

| | | |
|---|--|---|
| Type of Release Oil | Volume of Release 10 bbls | Volume Recovered 0 bbls |
| Source of Release Oil Tank | Date and Hour of Occurrence 1/18/14 12:12 pm | Date and Hour of Discovery 1/18/14 12:12 pm |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* The oil tank inside the battery overflowed, releasing 10 barrels of oil. The release moved south through the battery pad, over the lease road and into the pasture over Holly Energy's ROW. The pad was scraped to remove the wet soil. The area in the pasture was covered with soil to help absorb the standing oil and protect livestock/wildlife. | | |
| Describe Area Affected and Cleanup Action Taken.* The site will be assessed and then remediated to NMOC D and BLM regulations. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |

| |
|--|
| Signature: |
| Printed Name: Shawna Matthews |
| Title: Production Technician |
| E-mail Address: smatthews@burnettoil.com |
| Date: 1/29/14 Phone: (575) 322-7213 |

OIL CONSERVATION DIVISION

Signed By
Approved by Environmental Specialist:

Approval Date: 1/29/2014

Expiration Date: N/A

Conditions of Approval:

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:
4/4/14

Attached ☐

* Attach Additional Sheets If Necessary

2EP-2180