


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Complete appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NJMN 1403048842

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	State 27 #1 CTB	Facility Type	Gathering

Surface Owner	(State or Fed?)	Mineral Owner	API No.	30-015-29374
---------------	-----------------	---------------	---------	--------------

LOCATION OF RELEASE

use API #

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	24S	29E					Eddy County, NM

Latitude N 32.19473° Longitude W 103.97987°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	122 bbls	Volume Recovered	120 bbls
Source of Release	3 inch poly gas/water line from the facility to the main gas gathering system leaked	Date and Hour of Occurrence	01/06/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Kathy Purvis	Date and Hour	01/09/2014		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A leak in the 3 inch poly gas/water line from the facility to the main gas gathering system caused 122 bbls of produced water to spill onto the ground. 120 bbls of produced water were recovered via vacuum truck and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 5' x 100'. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 1-15-14 Phone: (575) 397-8216

Approved by Environmental Specialist:

Approval Date: JAN 29 2014

Expiration Date:

Conditions of Approval:

Remediation per UCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

March 1, 2014

Attached ☐

2RP-2172

* Attach Additional Sheets If Necessary