

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 27 2014

Form C-141
Revised August 8, 2011

NMOCD ARTESIA

Appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1406629354

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company - EOG Resources, Inc.	7377	Contact - Ryan Kainer
Address - 5509 Champions Drive, Midland, TX 79706		Telephone No. (432) 686-3662
Facility Name - Ross Draw 8 Fed #2H		Facility Type - Oil Well



Surface Owner - New Mexico & BLM	Mineral Owner - New Mexico & BLM	API No. 30-015-39099-00-X1
----------------------------------	----------------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter B	Section 8	Township 26S	Range 31E	Feet from the 330	North/South Line North	Feet from the 2240	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.0638 Longitude -103.8040

NATURE OF RELEASE

Type of Release - Crude	Volume of Release - 15 bbls	Volume Recovered - 9 bbls
Source of Release - Fill line left closed	Date and Hour of Occurrence: 2/26/2014, 2:00 PM	Date and Hour of Discovery 2/26/2014, 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffery Leking (NMOCD) & Jennifer Van Curen (BLM)	
By Whom? Ryan Kainer	Date and Hour 1/28/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Approximately 15 bbls of crude was released from a fill line being left closed by an oil hauler. Approximately 9 bbls were collected and the spill was contained within the pad location.		
Describe Area Affected and Cleanup Action Taken.* The impacted area will be excavated, stockpiled on poly-plastic, and transported to an approve disposal facility. Clean material will be backfilled within the excavated area to normal grade.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Ryan Kainer		Approved by Environmental Specialist: 
Title: Sr. Safety & Environmental Rep.	Approval Date: 3/7/14	Expiration Date:
E-mail Address: ryan_kainer@cogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/27/2014	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/2/14	

* Attach Additional Sheets If Necessary

22P 2186