

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 14 2014

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC 229137 Contact Robert McNeill  
Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077  
Facility Name Salada Vista 36 State #002 Facility Type Well Pad

Surface Owner State Mineral Owner Lease No. (API#) 30-015-40253

### LOCATION OF RELEASE

Unit Letter D	Section 31	Township 19S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 37.354 Longitude 103 54.997

### NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 15bbls of oil 5bbls of produced water	Volume Recovered 5bbls of oil 0bbls of produced water
Source of Release Hammer union	Date and Hour of Occurrence 01-09-2014	Date and Hour of Discovery 01-09-2014 12:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Hammer union started leaking on the wellhead. Replaced hammer union.		
Describe Area Affected and Cleanup Action Taken.* Initially 15bbls of oil and 5bbls of produced water were released. We were able to recover 5bbls of oil and 0bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

### OIL CONSERVATION DIVISION

Signature: *Robert Grubbs Jr.*

Printed Name: Robert Grubbs Jr.

Title: Senior Environmental Coordinator

E-mail Address: rgrubbs@concho.com

Date: 01-14-2014 Phone: 432-661-6601

Approved by District Supervisor:

Signed By *M. H. Brandon*

Approval Date: JAN 29 2014

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:

Attached ☐

\* Attach Additional Sheets If Necessary

March 1, 2014

2RP-2169