

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 10 2014

Form C-141  
Revised August 8, 2011

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nltmp 1407326842

OPERATOR

X Initial Report ☐ Final Report

Name of Company: Cimarex Energy Company	162683	Contact: Johnny Tittsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701		Telephone No. (432)250-2059
Facility Name: Bradley 14 Federal #1		Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner:	API No. 30-015-32672

LOCATION OF RELEASE

Unit Letter E	Section 14	Township 24S	Range 26E	Feet from the 1650	North/South Line FNL	Feet from the 990	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.22036 Longitude: -104.26897

NATURE OF RELEASE

Type of Release: Crude	Volume of Release: 16BBL	Volume Recovered: 8BBL
Source of Release: Oil Tank	Date & Hour of Occurrence: 3/8/14	Date & Hour of Discovery: 3/8/14 11:30 am
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Max Pfaff	
By Whom? Ronald Frederick	Date and Hour: 3/8/14 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



A hole developed in the bottom of oil tank #1, vac truck was called out to recover lost product.

Describe Area Affected and Cleanup Action Taken.\*

100'x12' plastic lined gravel berm. Impacted soil and gravel will be removed and hauled to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Johnny Tittsworth	Approval Date: 3-14-14	Expiration Date: NA
Title: Environmental Compliance Coordinator	Conditions of Approval:	
E-mail Address: jtittsworth@cimarex.com	Attached <input type="checkbox"/>	
Date: 3/10/14 Phone: (432)-250-2059	Remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4-14-14	

\* Attach Additional Sheets If Necessary

2RP 2212