


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
90 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHMP1409045328

Name of Company		COG OPERATING LLC 229137	OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701	Contact		Robert McNeill	
Facility Name		SRO SWD #102	Telephone No.		432-230-0077	
			Facility Type			
Surface Owner State			Mineral Owner			Lease No. (API#) 30-015-21398

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	26S	28E					Eddy

Latitude 32.04430 Longitude 104.09031

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water	10bbls	0bbls (Thick Gravel)
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
3" Vic check valve	03-20-2014	03-20-2014 09:00am
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" Vic check valve on discharge side of the produced water disposal pump. Replace the Vic check valve with a new one.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced water were released. We were able to recover 0bbls of produced water due to several inches of gravel. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Robert Grubbs Jr.	Approval Date: 3-31-14	Expiration Date: 1/14
Title: Senior Environmental Coordinator	Conditions of Approval: Final	
E-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 03-27-2014 Phone: 432-661-6601		

* Attach Additional Sheets If Necessary

2RP-2237