

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1000 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 27 2014

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA  
Submit Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

n HMP1409237494

Name of Company		Contact	
COG OPERATING LLC 229137		Robert McNeill	
Address 600 West Illinois Avenue, Midland, TX 79701		Telephone No. 432-230-0077	
Facility Name Loco Hills SWD 35 #001		Facility Type SWD	
Surface Owner State		Mineral Owner	
		Lease No. (API#) 30-015-31635	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	17S	30E					Eddy

Latitude 32.78561 Longitude 103.91967

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 1/4bbl of oil 10bbls of produced water	Volume Recovered 1/4bbl of oil 10bbls of produced water
Source of Release Load line	Date and Hour of Occurrence 01-17-2014	Date and Hour of Discovery 01-17-2014 6:45pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Driver drove off still attached to the load line. Replace the load line

Describe Area Affected and Cleanup Action Taken.\*

Initially, 1/4bbl of oil and 10bbls of produced water were released due to a water hauler driving off without disconnecting the load line. We were able to recover 1/4bbl of oil and 10bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Robert Grubbs Jr.		Approved by District Supervisor:	
Title: Senior Environmental Coordinator		Approval Date: 4-2-14	Expiration Date: NA
Email Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 01-17-2014 Phone: 432-661-6601		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Accepted for record  
NMOCD

2RP-2245