


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHMP 1408 738739

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Buho BQH State #1	API Number 30-015-38223	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. VB-679
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit/Letter M	Section 2	Township 16S	Range 29E	Feet from the 400'	North/South Line South	Feet from the 200'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

A 35 26S 28E Latitude 32.00513 Longitude 104.04950

NATURE OF RELEASE

Type of Release Oil	Volume of Release 15 B/O	Volume Recovered 15 B/O
Source of Release Production Tank	Date and Hour of Occurrence 3/7/2014; AM	Date and Hour of Discovery 3/7/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The oil tank overflowed. Water dump on heater was bad, causing oil and water to dump into the oil tank. The well was shut off and vacuum trucks were called in.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 8' X 100' (all released oil was contained in lined/bermed battery). Repairs were made, and all oil was recovered. Depth to Ground Water: >50-99' (approximately 70', per Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on battery being lined/bermed and all oil recovered, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Asher		Approved by District Supervisor:	
Title: Environmental Regulatory Agent		Approval Date: 3/28/14	Expiration Date: NA
E-mail Address: boba@yatespetroleum.com		Conditions of Approval:	
Date: Friday, March 21, 2014 Phone: 575-748-4217		2RP- Final	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-2232